



## The Standard ENGINE LOG

ASA-SE-2

8-25-11-13-28-22

Manufacturer Ly Comba	Model TO - 360-CIC6	
Serial 6-10762-51A	Type Certificate	
This engine is currently installed in aircraft: _		

Minimum Octane Fuel \_\_\_\_\_ Oil Grade Summer \_\_\_\_\_ Winter \_\_\_\_\_

Magneto Time \_\_\_\_\_ Point Setting \_\_\_\_\_ Firing Order \_\_\_\_\_

Spark Plug Gap

Engine Record General Information

Manufacturer's Recommended Overhaul at \_\_\_\_\_ hours

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
8/25/11 SMOH	7174.59		4742.99	Changed oil and Sitter. Serviced engine with Phillips 200050 and oil Sitter PIN CH48110-1. Serviced spark plugs. Cleaned engine and test row.
				ALP 2756658 Dason Pardis
				The
7				

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/21/11	7226,53		4794.93	Changed oil and Soller Serviced
SMOH	673.73	A makes a	62.00	engine with Phillips 20W50 and Sotter
	10			PIN CH48110-1. Replaced air falter
				PIN BA-10. Serviced sporte plags,
				Fre Lorned compression test # 18/80 # 278/80 # 4 78/80
-				C/W AD 08-14-07 Quel injection lines
	***			by visul inspection AD 08-14-07 next
				due at 7326,53 teach CIN AD
				11-15-10 NIA NOT installed,
				I cartify that this engine has been
				Inspected in accordence with a 100'
				Hour Tuspection and was determed
				to be in adrivorting condition
				All 2756658 Jason Puredes
				Ofer 5
				9.00

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/1/12	7279.6		4848.0	Changed oil and Salter Serviced engine
STOH	726.8			with PHIMPS 20050 and Siller 8mil
				CH48110-1. Serviced spork plus, s.
				cleared englie and fist for checked
				Sur locks.
				4.0
				ALP 2756658 Jase - Puradis
				The S
				7

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed	ections, Tests, Repairs and Alterations Is with Name, Rating and Certificate Number of Ility. (See back pages for other specific entries.)
	Date: 3-26- Tach: 7326			Aircraft # N3761F Engine  Total Time: 4894.55	Serial # L-10762-51A
	engine, rep	air front ba	affling, test rur AR fuel servo	n engine, C/W AD 11-26-04	d filter, Phillips 20W50, clean plugs, clean by inspection, next due 7426.15, AD engine inspected IAW an annual inspection
	Prepared By	Mull y: H. L. W	Vilson		
	Certification	# 31820	68IA		
4/24/12	7354.01 Smolt	801.2	4922,41	REMOVE LES	the Bon 3/82068 IA
				1 X nat yrue	51020024

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	il s	Comp nterna ee ye ompl neede	olete te al bear llow ta ete in d and	najor O.H. and inspect eardown ,replace cam, & all rings & parts ,replace case, ags ,upper, 4 cylinder spect and rebuild as return to service, same as aul .  1/28/19  1/28/19

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
_ [i	t this	ti	me Z	467.81 and date 4/28/19
re	placed	m	air.	Case Change TO360 C/C/c, baring pr# 18026098-mg/cham
- Sho	als, -	lappo	15 un	d lighter prit 5122877
	0 .			led at this time tact #
74	67.81	_, a	rrows	for further information end.
				Hacking 4635- -73829
		0	Gui	-73829

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)		
7 MAN	REPLA TER, C FROM DS ARE ENGINE HAL, PT AIRING	#1) 74 Ce S PEN 1 Re 1-JA 1-JA 1-JA	PARKI PARKI OLD FI CENT E OR P/ SBEEN APP D COND	VSPECTION COMPLETED TODAY, CK ) 77/80, #3) 77/80, #4) 75/80, CK MAGNETO, PLUGS REPLACE / GNITION, HARNESS, CHG LTER-SLIGHT A MOUNT OF NON-METALIC ENGINE REPAIRS, NO OIL LEAKS NOTED 'C/W OR NOT DUE NOW, I CERTIFY THAT INSPECTED T/A/W THE LYCOMINGS VE AND A 100 HR/ANNUAL/NSPECTION AND UTON; TTTACH 7469, I SMOH 016, 3		
31 July 2020 Annuial/100hr inspection completed today. Ck compression - all cyls >72/80, clean and gap spark plugs, ck mag timing, no leaks observed, chg oil and filter, open filter and no metal found, ck prop tracking and hub security and no leaks found. Engine runup normal with normal prop governor function. Using the lycoming service manual, Pt 43 App D, I certify that this engione has been inspected I/A/W an annual/100hr inspection and is in airworthy condition.  TTAF 7484, 6 TSMOH 168 31 July 2020 Attuit Usung 3242974 Att I TA						

AR TE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alt Entries must be endorsed with Name, Rating and Certificate N Technician or Repair Facility. (See back pages for other specific	umber of
wo: N37	61F 7-11-2021			Engine · page 1 of 2  PS  and Roberts Aircraft Service LLC	
N376	15			-C1C6, S/N: L-10762-51A August 09, 2021	7
	: 7513.21		1114G, 10-360- 1: 45.41	-C1C0, 3/N. L-10/02-31A August 03, 2021	
2. E	Champion Oil Engine Oil Fille PN: 75736 and Filler Tube Long Push Rod Tube that the above cing the current	Filter, Inst er Neck S Replaced , Installed es Not Saf work was t revision of	called (8) Phill afety Wire To Gasket. IAW: (1) SL72059 etied – Safeti performed in of the aircraft a	accordance with the current federal aviation regulations and and/ or its appliances maintenance publications. The aircraft an airworthy condition with respect to the work performed	
wo: N37	761F 7-11-2021	/-		Engine · page 2 of 2	
			Roberts	s and Roberts Afreraft Service IIC	
		R + R Aircra		441 Stoneside Trl · Fort Worth, TX 76244 · 817-360-0810	

X

1

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
			7525 5	4 TCMO 67.74
	DATE: 5/7/	23 TAC	CH. 7535.54	4 TSMO. 67.74
	RE: TEXR	ON LYC	OMING IO	0-360-C1C6
	SERIA	L# L-107	762-51A	
	I certify this	engine v	vas repaired	due to a sudden stoppage incident in accordance with
	Lycoming o	verhaul r	nanuals, AI	2004-10-10, and SB533A. All airworthiness directives ls on file under work order #1022.
	and release	tags attac	ned. Detail	is off the under work order #1022.
				STRAIGHT ERO
				AIRCRAFT ENGINES
		1		5614 Ruby St. Sw.
	1			Fort Mohave, Az. 86426
	Lynn Coot	er A&P #	563617475	Tel: 928-200-1754