


LEFT ENGINE

N318AC



McCAULEY

PROPELLER LOGBOOK

Closed
12/06/17

Installed on N310HC, C3DR839
 on 6/8/98 - ~~2549~~
 2549 *JAA*

Owner Name Quint-off, Inc. 304-255-5398

Address Box 1279, Beavers, WV, 25813

Propeller Model 3AF32C504-C

Blade Model G-82NEA-5.5

Hub Serial No. 980833

Blade Serial No. 1 RK130

2 RK131

3 RK149

4 _____

INSTALLATION HISTORY

Date	Aircraft Model & Registration No.	Engine Serial Number & Position
APR 14 1998	THIS PROPELLER WAS MANUFACTURED NEW AT MCCAULEY PROPELLER SYSTEMS, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE.	(M 209)
5-6-98	Installed deice boots MAINTENANCE RELEASE The propeller identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved to service. "Pertinent details of the repair are on file at this repair station under Work Order No. <u>NR-7313</u> Date <u>5-6-98</u> ." Signed <u><i>Gregory L. Evans</i></u> U. S. PROPELLER SERVICE, INC. FAA-YX4R690M GREENSBORO REGIONAL AIRPORT — GREENSBORO, NC 27419	

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
6/8/98	- 0 -	N/A	Installed N310HC 2549 TT	John H. Walker
6-8-98	- 0	N/A	Lt side 2549 TT	AP 19883 2549
7-1-98	3.0	N/A	Installed New HOBBS @ 155V; HOBBS "0" —	v jtu


NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
24 FEB-04	17055 631.00	N/A	DISASSEMBLED M'CAULEY PROPELLER S/N 980833, REPAIRED LEAK C/W SB 119A, 227B, 5L 86- 87-3, 00-2, 02-17, REASSEMBLED, GREASED, PAINTED & BALANCED BY H&H PROPELLER SERVICE, INC UNDER N.D. 13 H & H PROPELLER SERVICE, INC. 3439 SOUTH AVIATION DRIVE BURLINGTON MUNICIPAL AIRPORT BURLINGTON, N. C. 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437	John H. Walker

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
2/26/04	Hobbs 631.0		Installed on LT engine on N310HC after removal from H+H propeller. Used new nuts + O-Ring. Torqued to 50 ft lbs. Leak check good.	 211643573 A+P

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12