



ENGINE Type:	PW535A		ENGINE S/N:	PCE-DC0385			
	TSN:	2158.2	TSO:		TSHSI:		#2
	CSN:	2754	CSO:		CSHSI:		
<u>Part Description</u>	<u>Part Number</u>	<u>Serial Number</u>	<u>Mfg Limit</u>	<u>Eng. Cycle @ Installation</u>	<u>Part Cycle @ Installation</u>	<u>CSN/TSN</u>	<u>Remaining</u>
LP COMPRESSOR FAN ROTOR	3054281-01	A003YWX6	15,000	0	0	2,754	12,246
LP COMPRESSOR BOOST ROTOR	3041742-01	TXA1D6155	15,000	0	0	2,754	12,246
1ST STG. HP COMP ROTOR	3070301-01	A0044MHF	10,000	0	0	2,754	7,246
2ND STG. HP COMP ROTOR	3056210-01	EAAE000L141	13,500	0	0	2,754	10,746
CENTRIFUGAL IMPELLER	3052661-01	A0047FWF	13,500	0	0	2,754	10,746
1ST STAGE TURBINE DISK	3053331-01	A00483X1	10,000	0	0	2,754	7,246
2ND STAGE TURBINE DISK	3053812-01	A0047WCF	13,500	0	0	2,754	10,746
3RD STAGE TURBINE DISK	3053743-01	A004861R	13,500	0	0	2,754	10,746
HIGH TURBINE BLADES (HRS)	3076231-01	unk		0	0	2158.2 TSN	
ACCESSORIES							
<u>PART DESCRIPTION</u>	<u>PART NUMBER</u>	<u>SERIAL NUMBER</u>	<u>Part T.A. Install</u>	<u>TSN</u>	<u>TSO</u>	<u>STATUS</u>	
FUEL CONTROL-HYDRO MECH	3042081-05						
EXCITER BOX	3052328-03						
PUMP ASSY-OIL	3052415-01	unk	0.00	0.00			
EXCHANGER-HEAT, FUEL OIL	3052640-01						
CONTROL-BLEED VALVE	3052768-02						
VALVE-FLOW DIVIDER	3052780-02						
NOTES: All above information was gathered from CAMP Report Dated: 5/23/2023							
NOTES:							