

Tech Tip # 105

Laundering Instructions for Comfort Flow and Comfort Scrape Mats

Comfort Flow and Comfort Scrape™ mats are fully launderable mats that perform great as anti-fatigue and flow-through mats in both wet and dry environments. They are ideal for Value Lease applications and do not require aggressive wash procedures or drying. Comfort Flow mats can be washed periodically to remove oil, grease and soil. The formula shown below does not require extensive mechanical action. Its main purpose is to dissolve grease residue by using hot water to emulsify oils and grease.

	Process	Comments	Time	Water Level	Temperature
1.	Flush		2-3 Min.	High	120°F(49°C)
2.	Break		5-10 Min.	High	140°F(60°C)
3.	Rinse	Optional	2 Min.	High	120°F(49°C)
4.	Rinse		2 Min.	High	Cold

Lay mats flat following removal from washer or dryer. Allow mats to cool before rolling. Roll mats nap out for delivery.

- Do not use high pH detergents, alkali or solvents. The break should not exceed a pH of 9.5. Use a low pH non-ionic detergent. 2-4 oz./ 100# of mats. Consult with your chemical supplier for exact amounts.