



FIRMWARE RELEASE NOTES

Version 6.2.147.9 (BrightSign 4Kx42, XDx32, HDx22, LSx22)

Changes Since 6.2.147.2

Bug Fixes

- 29592: A cross-site-scripting vulnerability associated with the Diagnostic Web Server has been patched.
- 29667: Adding certain characters to the */storage.html* URL on the Diagnostic Web Server no longer allows a credentialed user to view hidden file paths.