

BrightSign®

FIRMWARE RELEASE NOTES

Version 7.1.95

BrightSign 4Kx42, XDx32, HDx22

Changes Since 7.1.81

End User

Bug Fixes

- 31866: The WiFi LED now flashes correctly when a wireless module is connecting to the network.
- 28590: YouTube live streaming playback has been fixed.
- 31726: Streaming video playback with the G.711 and G.726 audio codecs now works.

Developer

Improvements

- The *roHtmlWidget* and *roUrlTransfer* objects now use the same set of CA certificates, which can be modified using *roKeyStore*.
- The *BSDatagramSocket* object now supports IPv6 multicast and source-specific multicast.
- The *roKeyStore* object now supports extending or replacing the default set of CAs on the player.