

**BrightSign®**

# FIRMWARE RELEASE NOTES

Version 6.2.63.2 (BrightSign XTx43, XDx33)

## Changes Since 6.2.63

### Bug Fixes

- XTx43 and XDx33 players no longer exhibit a spontaneous reboot issue.