



FIRMWARE RELEASE NOTES

Version 7.1.53 (BrightSign XTx44, XDx34)

Changes Since 7.1.50

New Features

- Support for PKCS8 private key parsing

Improvements

- Encrypted playback APIs now support string keys in addition to hex keys.

Bug Fixes

- Players no longer crash when reading a directory from a broken filesystem.

Known Issues

- HDCP 1.4 does not work with HDMI input or output that is hotplugged after the player boots up. Connect HDMI input/output cables before boot to ensure correct HDCP 1.4 functionality.
- (XT1144) Players cannot output to HDCP 2.2 displays from an HDMI input source that uses HDCP 1.4.