

The Standard

AIRCRAFT LOG

ASA-SA-1

Aircraft Record General Information	
Manufacturer VANS	Model RV-12
Serial 120438	11 11 07 0
Date of Manufacture SRPT 1	7, 2012
Engine(s) currently installed:	
Manufacturer RoTAX Model	912 ULS Serial 6776980
Manufacturer Model	Serial
Propeller(s) currently installed:	
Manufacturer SENSIZNICIT	Model _ ZAOR 5 R 70 EN -V
HUB Model Serial	2AOR5-F 10-10-16 Serial
Blade ModelSerial	26385 JAR Serial 49/56 10-10-16 Serial
Blade Model Serial	2650+3PK Serial 4917310-10-16 Serial

The second secon

YEAR:	TACH FLIGHT TIME IN Entries must be endorsed with Name, Rating and Certificate Number of Technicia				
DATE				Facility. (See back pages for other specific entries.)	
9/17/20)12 Ai	ircraft T	T:0.0	Time in Service: 0.0	
have co	ompletely	Inspecto	ed this airc	craft in Accordance with Appendix "D" to part 43 and Vans	_
urcraft	Inc Consti	ruction a	and Maint	enance Manuals and it is ready for the FAA ELSA	_
21.191(i)(2)) Airv	vorthine	ess Inspect	ion. This is a Vans Aircraft Inc; RV-12, Serial# 120438;	
N48ZG	Aircraft. A	All appli	icable AD'	s through Biweekly 2012-18 and manufacture's Service	
				tify that this engine, airframe, and propeller have inspected	
nd were	determin	ed to be	in a cond	ition for safe operation and suitable for flight	
ohn Ny	s (Owner's	s Agent)		In A Hy	
			//		

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

09/17/2012 A

Aircraft TT: 0.0

Time in Service: 0.0

I have inspected this aircraft and found it complies with the requirements of FAR 21.191 (i)(2). Certificate of Special Airworthiness (8130.7) along with Phase I and Phase II Operating

Limitations were issued this date with unlimited expiration. The next inspection (condition inspection) is due 09/31/2013. Bart B. Dalton-----

DAR T700789SW

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
OUT	2,2013	2	5,6	I CENTIFY THAT THE PRESCUESTO FULLY
				TEST HOURS HAVE BEEN COMPLETED AND THE
				AIRCRAFT 15 CONMONABLE THROUGHOUT 15
				Norman Ramon D= SPHADS + THROUGHOUR ALL
				DECENTING CHARACTERISTICS OF DESIGN FEATURES
				AND 15 SAFE FOR DEPATION. THE FLICHT TEST
				WAS COMPLETED UNDER THE FAVORING CONDITIONS!
				MAXIMAM DEMANNE WEIGHT, MAXIMUM DEMINSTRATES
				ALRSRED, + MINIMUM DEMONSTRATED STALL
				SPEED. John MAR

0-00		20.	or was the state of the state of	
YEAR: 2013 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
03/08			27.0 hrs	Rotax initial oil charge + hiller call west well. 3 Qts.
			* 2	Rotax Filter. 3 Ats of Shell. Oil Filter or oil analysisno
			7 Rot	1 10 200 hrs for 5 pluge o Toner J. D. Pechandson omaka.
05/01			30.0	Repair of cracked Right side or heal part o Fiberglow + paint
				Return to service, owner & Richardson

Advanced Air, Inc. 16801 McCandless Lane, Council Bluffs, LA 51503 712-323-2173

Date: 20May2013 W.O. 5296 Reg# N48ZG Tach:

Aircraft Total Time:

Troubleshot erroneous fuel pressures and found sensor to be bad. Ordered new sensor. Old style VDO sensor no longer available. Installed new style Kaylico sensor p/n 101690-000. Test ran aircraft, no discrepancies noted.

YEAR: 2013/14 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
09/23/			443	In accordance with 43 Appendix Dannuel Check list and was determined to be in condition for Safe operation
09/23/			443	Jame Do Richardson 15a RT # 370 45240 ELT battery good til 12 - 2016. ELT annual
				Inspection showed unit to be in condition for sofe operation. Jana D. Richardson LSA RI# 370 4524.
1/23/B			443	Service Bullotin 12-09-26, Loose main Landing goon attach hardware, Inspected & Found hardware Souted, torquet
				corplete & Finish this SB. It Richardson RI# 3704524
7-28-14			98.3	according w/ 43 appender D arrest check list and was detaried
		ELT	Inspected to	to be in sole operations James & Ruhardion LSARI#3704524

YEAR: 20/4 / DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11-23-14	·		110,3	Steve Przewic lewski & myself put uf 470 capacita below
	1			Buen & Redwine on Fuel PSI Kavlico sensor to quest sensor.
1-15-15			118.50	TROY Alves & my solfcharged out + new fitter, 3 cts all
	\			went well . Mag. plus La Kome but relatively little folling
				(915 hrs between oil change) (Montes owner J. D. Richardson
_ 10/12/20	015		Air	reraft Total Time: 148.7hrs Aircraft Tach Time: 148.7hrs

12/2015 Aircraft Total Time: 148.7hrs

Aircraft Tach Time: 148.7hrs

- 100hr/Annual Condition inspection performed in accordance with Van's RV-12 Maintenance Manual. Removed panels, performed inspection and reinstalled panels. Checked flight controls. Landing gear inspected. Main landing gear wheel bearings cleaned, inspected, and repacked. Brake fluid,
 brake pads replaced, and calipers checked. ELT inspected in accordance with FAR 91-207(D). Battery replacement due Dec 2016. Intake air filter inspected. Lubed and checked aircraft as per RV-12 100br/Appual Condition inspection sheek list and Appandix D of Part 43. Checked Aircraft has per RV-12 100br/Appual Condition inspection sheek list and Appandix D of Part 43. Checked Aircraft has a per RV-12 100br/Appual Condition inspection sheek list and Appandix D of Part 43. Checked Aircraft has a per RV-12 100br/Appual Condition inspection sheek list and Appandix D of Part 43. Checked Aircraft has a per RV-12 100br/Appual Condition inspection sheek list and Appandix D of Part 43. Checked Aircraft has a per RV-12 100br/Appual Condition inspection sheek list and Appandix D of Part 43.
- inspected. Lubed and checked aircraft as per RV-12 100hr/Annual Condition inspection check list and Appendix D of Part 43. Checked Airworthiness Directives and Van's Safety Directives.

"I certify that this aircraft has been inspected in accordance with the scope and detail of Appendix D of Part 43, and Van's RV-12 100hr/Annual Condition inspection check list, and found to be in a condition for safe operation". Next inspection due at 10/12/2016

tephen Przemielewski

A&P 3108825

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10-12-15			148.0	De new Brake pads on the 2 Back.	8-19-16			355.0	AIR in backtires oil change + filter (84hus between Lauge)
12-20-15			203.50	New Brake pads on possenger Side . Of (Brake Hind)			4	WAA-1	есн
1-20-16			203,50	Pilots Side new wheel " New tube in tire whel				S. 132 nd St. na, NE 6813	Millard Airport AIRFRAME 7
12-1-16			203,50	oil 3 Fitter Change. Rotax, JA Richardson Builder.			Septer	mber 26, 201	6 N48ZG S/N 120438 Hobbs: 363.4
3-12-16			250.50				systen	n. Balanced	ropeller system using Aces Model 2020HR Probalancer Analyzer system to .02ips @ 292 degrees. Installed balance weight 17 grams on
4-2-16		-	241.08	Change Oil: No new little Oil only OD Richardson			_ to serv	ller spinner b	mothy X- Shrum
,5-25-16			314,00	I May Time on bed man Oit of adjustment & Philadson		,	Timo	othy K. Shrun	n A&P3471627IA
6-8-16			318.00	Refolmed Bing Carles (1 st time w/electronic Continutes)	t -				

The second of th

								200	
YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
dance with tion inspectify that the tion chec	th FAR 91-207 ection check linis aircraft has k list, and four	7(D). Batter ist and App been inspe	formed in accordance of the ac	Mow Prop heedswheel part, reado hole Gixeb In Loft Wing Phase OK to Fly JDR 3704524 It Total Time: 391.7hrs Aircraft Tach Time: 391.7hrs In Loft Wing Phase OK to Fly JDR 3704524 Aircraft Tach Time: 391.7hrs Aircraft Tach Time: 391.7hrs In Loft Wing Phase OK to Fly JDR 3704524 Aircraft Tach Time: 391.7hrs Aircraft Tach Time: 391.7hrs In Loft Wing Phase OK to Fly JDR 3704524 Aircraft Tach Time: 391.7hrs Aircraft	11-28-16	Damage to I Drilled riv Replaced	eft wing i rets holdi one rib, on new wi	RV-12 nboard leading skin, ren P/N W-120 ng skin, P/N 3-1-17	Rese landinger Replaced Wing has complete Mew Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Skin Where Snall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picked Shall hole was I contified place is Safe to Hy Picke
				Stephen Przemielewski A&P 3108825	11-28-16			391,7	ELT battery replaced FOR Emergency use, 3704524
1					1-17-17	,		406	New Voltage Regulator (Rectifier) James Rechardson 3704524
					2-16-17			410	RR broke coliples Leaking. Freed. Ocage Richmond Fame Richardson 37045

	YEAR: RECORDING TODAY'S TOTAL Description of Inspections Tests Repairs and Alternations													
DATE	TACH TIME	TODAY'S FLIGHT	TIME IN SERVICE	Description of Inspections, Tes Entries must be endorsed with Name, Facility. (See back pages for other spec	Rating and Certificate Number of Technician or Repair	YEAR: 20/8	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)				
5-13-17			457	Oil change; new Filter	(102 hrs between changes a Calvin	1-25-18			542	oil change, New Fifter (85 hours between oil changes)				
				Said och was to Liquid; al	not bad) Jano Richards on 3704524					100LL gosdine was used approximately 20% of time of Richard Son				
7-26-17			488	8 New Spark plugs; N	M= 20 = 2 20 Ft pols J. Richardson 3704524	3-26-18			548	Front whoel bearing broke o wheel loose o meeded 3704524				
				(238 hu between chang	ges of 5. plugs)					new wheel + new bearings of Richardon 3704524				
10/15/2017	7		Airer	raft Total Time: 512.5hrs	Aircraft Tach Time: 512.5hrs	9-27-18			627	oil change New Filter J. Richardson 3704524(85h)				
100hr/Ann reinstalled	ual Condition	inspection p	performed in acontrols. Landin	ccordance with Van's RV-12 Maintenance	Manual. Removed panels, performed inspection and replaced, and calipers checked. ELT inspected in	10-15-18	-		628	annual condition inspection Certified goods				
accordance	e with FAR 91-	207(D). Ba	attery replacem	nent due Nov 2022. Intake air filter inspecte	ed. Lubed and checked aircraft as per RV-12 100hr/Annual					Jane D. Hickardson 3704524				
2			200	Part 43. Checked Airworthiness Directives		10-16-18			629	Note: all Full foil L'inavare Teflon, Last forever				
"I certify ti	hat this aircraft check list, and	has been in found to be	nspected in acc e in a condition	cordance with the scope and detail of Appen in for safe operation". Ext, inspection due a	dix D of Part 43, and Van's RV-12 100hr/Annual Condition t 10/30/2018					Giorginal lines)				
			T.,	Stephen Przepielewski	A&P 3108825	1-1-19			629	Replaced the two main tires & tubes. all new now				
			5/2							Janes & Richardson 3704524				
12-12-17			590		aren. Puton New Pada. Regressel	8-1-19			700	oil change New Litter, 1st time to completely clean				
				bookrings. Noise still 7	Leve J. Richardson 370452A	1			i, k	oil tank. No leaded residue found. ID 3204524				

VEAR	RECORDING	TODAY'S	TOTAL	Description of Inspections Tosts Panaire and All					
YEAR:	TACH TIME	FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
53-2-19			711	8 spark plugs charged (223 his between change) NM 20.	10-22-21			877	Of change new felter JD Richardson 3704524 84 hours
10-13-19			7/7		10-23-21			877	annual contition Impertion. Coetified good 3704524
75-25-20			779	5 D# coot Petch Trin Inspection. Found the baito be	10-23-22			946	annual condition Inspection a Certified good J. Ruhardon
-				Straight of good for operation, Resheck@ 1,000 km. Jana Richarton	10-29-22			946	8 Spark pluge Changel (235 hrs) NM = 20 go Pickartson
5-25-20			779		10-30-22			946	Gowling Loose : Tower Right cowling plans hings repaired
				Found none w/my cyes. Jama Richardia	4-8-23			962	oil change new filter & DRichardon 3704524 85 hrs
7-23-20			793	Oil change change Fifter Dechardson 3704529	8-2-23			962	New RS Brake line: New Broke pads & D Pulpardson 3704524
9-25-20			808.5	annual condition Inspection. Certified good 3 704524	10-20-23	1		982	annual Condition Inspection, Certified good . I. Richardson
11-15-20			81925	Mew Voltage Regulator; Lockwood F1. \$ 150 Jo Richardon 3704524	6-27-24			990	Repaired muffler; installed now orl sensa, wilter, Ft. Calhoun
(H15-20			819.5	Man Odessy Pc 680 battery; arrayon J. D. Richardson 3 704524	10-30-24			1,030	arruel contition Inspection contified good 1 Prichason
6-8-21			844.0	1st time cleaned revited Bing an fathers 10 Puladin 3704524	5-10-25	1		1,051	Stop gop hole drilled in Side Goeoling. Liside. OK to Return to somuce
12				Rotax seemed to Run better, quieter & smoother	-			•	6
\				The state of the s	ļ				