## WOOD PROPELLER LOG BOOK



## SENSENICH WOOD PROPELLER CO., INC. PLANT CITY, FL

www.sensenich.com

This log book is to be kept with the propeller for recording of all propeller maintenance performed

Propositer Maintenance Record

Fropeller Model Number W72 CK 42 TC89/

Propeller Serial Number AL 7201

Ray a, Pre A+P 2172799

Size of Steel		Recommended Wrench Torque Range		
Aircraft Bolt				
Spec.	Dia. (in.)	inlb.	ftlb.	nm.
AN4	1/4	120 to 140	10 to 12	14 to 16
AN5	5/16	130 to 160	11 to 13	15 to 18
AN6	3/8	175 to 225	15 to 19	20 to 25
AN7	7/16	225 to 275	19 to 23	25 to 31
AN8	1/2	275 to 325	23 to 27	31 to 37
AN10	5/8	325 to 375	27 to 31	37 to 42

CAUTION! Torque recommendations do not consider variations of thread condition, and assumes that the threads of the bolts, nuts, or drive bushings are clean.

Maintaining proper bolt torque is the most important maintenance item for a wooden propeller.

## DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS AND MINOR ADJUSTMENTS

CERTICE BOLLETING, CERTICE LETTERS AND IMPORTANCE INC.						
	7		T			
DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE			
3-1-2021	1209 AM	wrotall on N34067 NEW Pay	Rex di Por			
6-16-2021	1838,7 hs	Annal inspection	Rent Pa A 12/42/99			
8-19-2022	1847.5	Installed on A-65-8 S/N 538-7968	on BC-65 taylorent			
	3	Inspected + tracked, Annual lasp this date &	m 2Pm: AAP 3518496 14			
11-01-2022	1857,8	RE-CHECKED BOLT TO POVE TO 18 F1, 18. DER TABLE 2 PROPENER INSTRUMENTOUS	mark Callen 9+10 430908681			
8-19-23	1872.2	Inspected VA/W Annual Insp.	Dyn 26 A+D 35K49614			
			, ,			
8-12-25	1919.0	Inspected 1/A/W Annual (1150.	An 2 Var Af P3 \$ 18496 14			
			,			