


Auto Calibration



Weight display

ON/OFF buttons
(Race On = EC2000 ON)

Weight Precision:
On = 100g; Off = 500g

Auto Calibrate
Press Ø → Display shows "On"

Back to zero (0)
Press 0 to set scales to zero

More weight precision means that weighing may take 1 or 2 seconds longer !