



B9Creator Z Axis Motor Problems



- 1.) Run Gold arm all the way up and down to feel for any catching.



2.) Unscrew the gold arm from the back-lash nut.



3.) Slide the gold arm up and down to feel for any catching



4.) If you feel any catching, look for burrs on the z-threads and/or the slide rail. Also try adding a small amount of lithium grease to the z-threads, and a small amount of 3-in-1 oil to the z-slide rail.