

CHECKER MOTORS CORPORATION
Kalamazoo, Michigan 49007

SERVICE BULLETIN NO. K-17-73
August 9, 1973

MODEL 1973 NEUTRAL SWITCH ASSEMBLY CHANGE
Taxicab-Marathon-Aerobus
(After Chassis No. 35579)

A change in a Neutral Switch Assembly furnished in the Taxicab and Marathon has been necessary to accommodate the new Front Seat Belt Starter Interlock System furnished in Model 1973 Taxicabs and Marathons after chassis no. 35579.

The Neutral Switch furnished in the Aerobus was not changed.

IMPORTANT: Check page 2 of this Service Bulletin when ordering a service replacement Neutral Switch Assembly for any Checker vehicle after above noted chassis number.

Insert this Service Bulletin in the front or rear of Group 8 in your Checker Parts Catalog dated September, 1971.

Parts and Service Division

STRG. COL. & WHEEL ASM.			ALL M O D E L S	GROUP 8						
ILLUS. KEY	PART NO.	DESCRIPTION		1	2	3	4	5	6	7
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8
		STRG. COLUMN - FUNCTION LOCKING, ENERGY ABSORBING PLUS ASSO- CIATED PARTS-USE W/TURBO HYDRA-MATIC TRANS. (MODEL 400)								
		(Taxicab - Marathon - Aerobus)								
		(After Chassis No. 35579)								
		NOTE: Refer To Service Bulletin No. K-5-73, Dated March 19, 1973, Page 3.								
20B-5	705054	SWITCH ASM. - Neutral Start								1
	705308	SWITCH ASM. - Neutral Start (New Part)	1	1	1	1	1			
		NOTE: All Other Parts Listed Under "Strg. Column - Function Locking, Energy Absorbing Plus Associated Parts" In Service Bulletin No. K-5-73 Dated March 19, 1973, Page 3 Remain In Effect After Chassis No. 35579.								