

CHECKER MOTORS CORPORATION
Kalamazoo, Michigan 49007

SERVICE BULLETIN NO K-24-73
August 21, 1973

MODEL 1973 TOOL CHANGES
Taxicab-Marathon-Aerobus
After Chassis No. 35915

In order to accommodate the new Front and Rear Bumper Installations (Refer Service Bulletin No.K-21-73) a new Bumper Jack has been furnished in all Model 1973 Taxicabs and Marathons, after chassis no. 35915. No change was made in the Aerobus unit.

The identification and model usage of the new Bumper Jack, as well as the Aerobus unit that did not change, are noted on page 2 of this Service Bulletin to facilitate ordering service replacement parts when needed.

IMPORTANT: Be sure and check this Service Bulletin when ordering any service replacement Tools for any Checker vehicle after above noted chassis number.

Insert this Service Bulletin in the front of Group 33 in your Checker Parts Catalog dated September, 1971.

Parts and Service Division

TOOLS

ILLUS. KEY	PART NO.	DESCRIPTION	ALL MODELS	GROUP 33								
				1	2	3	4	5	6	7		
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8		
		TOOLS Taxicab-Marathon (After Chassis No. 35915)										
	705254	COLUMN & BODY ASM. - Bumper Jack		1	1	1	1	1				
	705409	BASE ASM. - Bumper Jack		1	1	1	1	1				
	704922	WRENCH - Wheel Lug		1	1	1	1	1				
		TOOLS Aerobus (After Chassis No. 35915)										
	705047	JACK ASM. - Scissors (4-1 Gear Red.) W/Handle										1
	98407	WRENCH - Wheel Lug										1