

CHECKER MOTORS CORPORATION  
Kalamazoo, Michigan 49007

SERVICE BULLETIN NO. K-25-73  
August 22, 1973

MODEL 1973 EXHAUST SYSTEM CHANGE  
Taxicab-Marathon-Aerobus  
After Chassis No. 35915

A new Exhaust System Tail Pipe has been installed in all Model 1973 Checker vehicles after chassis no. 35915.

The identification and model usage of the new Exhaust System Tail Pipe is noted on page 2 of this Service Bulletin.

IMPORTANT: Be sure and check this Service Bulletin when ordering a service replacement Exhaust Tail Pipe for any Checker vehicle after above noted chassis number.

Insert this Service Bulletin in the front or rear of Group 15 in your Checker Parts Catalog dated September, 1971.

Parts and Service Division

EXHAUST SYSTEM			ALL MODELS	GROUP 15						
ILLUS. KEY	PART NO.	DESCRIPTION		1	2	3	4	5	6	7
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8
EXHAUST SYSTEM TAXICAB AND MARATHON 6 And 8 Cylinder Engines (After Chassis No. 35915)										
		Refer to Service Bulletin No. K-11-73 Dated June 15, 1973, page 1.								
51A-24	702624	PIPE - Exhaust Tail (Replaced by #706461)								
	706461	PIPE - Exhaust Tail	1	1	1	1	1			
EXHAUST SYSTEM - AEROBUS 8 Cylinder Engines (After Chassis No. 35915)										
		Refer to Service Bulletin No. K-11-73 Dated June 15, 1973, Page 3.								
52A-21	702624	PIPE - Exhaust Tail (Replaced by #706461)								
	706461	PIPE - Exhaust Tail								1