

CHECKER MOTORS CORPORATION
KALAMAZOO, MICHIGAN 49007

SERVICE BULLETIN NO. K-26-73
August 23 , 1973

MODEL 1973 EXTERIOR SIDE MOLDING CHANGES
Taxicab-Marathon-Aerobus
After Chassis No. 35707

The current production Exterior Side Metal Moldings have been replaced in production with an adhesive backed extruded Vinyl Molding after above noted chassis number.

Service replacement Vinyl Moldings are located and identified as to vehicle model usage, in this Service Bulletin, per following references.

<u>Description</u>	<u>Page No.</u>
MOLDING - FRONT DOOR SIDE Taxicab-Marathon-Aerobus.....	1
MOLDING - REAR DOOR SIDE Taxicab-Marathon-Aerobus.....	1
MOLDING - CENTER DOOR SIDE Aerobus.....	2
MOLDING - FRONT FENDER SIDE Taxicab-Marathon-Aerobus.....	3
MOLDING - REAR FENDER SIDE Taxicab-Marathon Sedan.....	3
MOLDING - REAR FENDER SIDE Station Wagon.....	4
MOLDING - REAR FENDER SIDE Aerobus.....	4

IMPORTANT: Be sure and check this Service Bulletin when ordering service replacement Exterior Side Moldings for any Checker vehicle after above noted chassis number.

Insert this Service Bulletin in the front or rear of Group 27 in your Checker Parts Catalog dated September, 1971.

Parts and Service Department

Attachment

SIDE EXTERIOR		DESCRIPTION	ALL MODELS	GROUP 27										
ILLUS. KEY	PART NO.			1	2	3	4	5	6	7				
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8				
		DOOR ACCESSORY PARTS - FRONT Taxicab-Marathon-Aerobus (After Chassis No. 35707)												
		Refer To Service Bulletin No. K-45-72 Dated November 29, 1972 Page 2 And To Checker Parts Catalog Dated September 1971, Page 27-9.												
	640414	MOLDING - Front Door Side (Replaced By #646666)												
	646666	MOLDING - Front Door Side (New Part)	*2	*2	2	2	2						*2	
	626594	RETAINER ASM. - Frt. Door Side Trim Mldg. Rr. Mldg. (Cancelled)												
	626489	NUT & SEALER ASM. - Frt. Door Side Trim Mldg. Rear Mtg. (#10 - 24) (Cancelled)												
		NOTE: All Other Parts Listed Under "Door Accessory Parts - Front" In Service Bulletin No. K-45-72 Dated November 29, 1972 Page 2 And In Checker Parts Catalog Dated September 1971, Page 27-9 Remain In Effect After Chassis No. 35707.												
		DOOR ACCESSORY PARTS - REAR Taxicab-Marathon-Aerobus (After Chassis No. 35707)												
		Refer To Service Bulletin No. K-45-73 Dated November 29, 1972 Page 4 And To Checker Parts Catalog Dated September 1971 Page 27-15.												
	640389	MOLDING - Rear Door Side (Replaced By #646667)												
	646667	MOLDING - Rear Door Side (New Part)	*2		2		2						*2	
	642205	MOLDING - Rear Door Side (Replaced By #646669)												
	646669	MOLDING - Rear Door Side (New Part)		*2		2								
	626594	RETAINER ASM. - Side Molding (Cancelled)												
		NOTE: All Other Parts Listed Under "Door Accessory Parts - Rear" In Service Bulletin No. K-45-72 Dated November 29, 1972 Page 4 And In Checker Parts Catalog Dated September 1971 Page 27-15 Remain In Effect After Chassis No. 35707.												
		* (OPTIONAL)												

SIDE EXTERIOR

ILLUS. KEY	PART NO.	DESCRIPTION	ALL MODELS	GROUP 27							
				1	2	3	4	5	6	7	
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8	
		DOOR ACCESSORY PARTS - CENTER Aerobus (After Chassis No. 35707)									
		Refer To Service Bulletin No, K-45-72 Dated November 29, 1972 Page 5 And To Checker Parts Catalog Dated September 1971 Page 27-22.									
	640731	MOLDING - Center Door Side RH & LH Trim (Replaced By #646667)									
	646667	MOLDING - Center Door Side RH & LH Trim (New Part)									*4
	626594	RETAINER - Center Door Side Trim Molding (Cancelled)									
		NOTE: All Other Parts Listed Under "Door Accessory Parts - Center" In Service Bulletin No. K-45-72 Dated November 29, 1972 Page 5 And In Checker Parts Catalog Dated September 1971 Page 27-22 Remain In Effect After Chassis No. 35707 .									
		* (OPTIONAL)									

SIDE EXTERIOR		DESCRIPTION	ALL MODELS	GROUP 27						
ILLUS. KEY	PART NO.			1	2	3	4	5	6	7
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8
		FENDER INSTALLATION - REAR Station Wagon (After Chassis No. 35707)								
		Refer To Checker Parts Catalog Dated September 1971, Page 28-9 & 10								
	646668	MOLDING - Rear Fender (New Part)					2			
		NOTE: All Other Parts Listed Under "Fender Installation - Rear" In Checker Parts Catalog Dated September 1971, Page 28-9 & 10, Remain In Effect After Chassis No. 35707.								
		FENDER INSTALLATION - REAR Aerobus (After Chassis No. 35707)								
		Refer To Checker Parts Catalog Dated September 1971, Page 28-15.								
	646665	MOLDING - Rear Fender (New Part)								* 2
		NOTE: All Other Parts Listed Under "Fender Installation - Rear" In Checker Parts Catalog Dated September 1971, Page 28-15 Remain In Effect After Chassis No. 35707.								
		* (OPTIONAL)								

SIDE EXTERIOR

ILLUS. KEY	PART NO.	DESCRIPTION	ALL MODELS	GROUP 27								
				1	2	3	4	5	6	7		
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8		
		FENDER INSTALLATION - FRONT Taxicab-Marathon-Aerobus (After Chassis No. 35707)										
		Refer To Checker Parts Catalog Dated September 1971, Page 26-2.										
642205		MOLDING - Frt. Fender Side RH & LH Trim (Replaced By #646665)										
646665		MOLDING - Frt. Fender Side RH & LH Trim (New Part)	*2	*2	2	2	2				*2	
626488		RETAINER ASM. - Frt. Fender Side Trim Molding - Frt. Mtg. (Cancelled)										
626489		NUT & SEALER ASM. - Frt. Fender Side Trim Molding Frt. (#10 - 24) (Cancelled)										
626594		RETAINER ASM. - Frt. Fender Side Trim Molding (Cancelled)										
		NOTE: All Other Parts Listed Under "Fender Installation - Front" In Checker Parts Catalog Dated September 1971, Page 26-2, Remain In Effect After Chassis No. 35707.										
		FENDER INSTALLATION - REAR Taxicab-Marathon Sedan (After Chassis No. 35707)										
		Refer To Checker Parts Catalog Dated September 1971, Page 28-3.										
646668		MOLDING - Rear Fender (New Part)	*2	*2	2	2						
		NOTE: All Other Parts Listed Under "Fender Installation - Rear" In Checker Parts Catalog Dated September 1971, Page 28-3, Remain In Effect After Chassis No. 35707.										
		* (OPTIONAL)										