

CHECKER MOTORS CORPORATION
Kalamazoo, Michigan 49007

SERVICE BULLETIN NO. K-27-73
August 24, 1973

MODEL 1973 BRAKE PEDAL ASSEMBLY CHANGES
Taxicab-Marathon-Aerobus
After Chassis No. 33403

A new Brake Pedal Assembly has been installed in all Model 1973 Checker vehicles after chassis no. 33403.

Service replacement parts available for the new Brake Pedal Assembly are noted on page 2 of this Service Bulletin.

IMPORTANT: Be sure and check this Service Bulletin when ordering any service replacement parts for the Brake Pedal Assembly for any Checker vehicle after above noted chassis number.

Insert this Service Bulletin in the front or rear of Group 5 in your Checker Parts Catalog dated September, 1971.

Parts and Service Department

BRAKES

ILLUS. KEY	PART NO.	DESCRIPTION	ALL MODELS	GROUP 5								
				1	2	3	4	5	6	7		
				A 11	A 11 E	A 12	A 12 E	A 12 W	A 12 W 6	A 12 W 8		
BRAKE PEDAL AND SUPPORT - POWER Taxicab-Marathon-Aerobus (After Chassis No. 33403)												
NOTE: Refer To Checker Parts Catalog Dated September 1971, Page 5-6.												
9C-2	705161	PEDAL ASM. - Brake Complete (Replaces #703997)	1									
	705160	PEDAL ASM. BRAKE - Welded	1									
	702808	BUSHING - Pedal	2									
	706297	COVER - Brake Pedal Pad (Replaces #94431)	1									
	701672	COVER ASM. - Brake Pedal (Cancelled)										
	9416430	NUT - Cover Asm. To Brake Pedal Pad Mtg. (1/4 - 28 Type N)(Cancelled)										
NOTE: When Ordering Brake Pedal And Support Plus Associated Parts For Service Replacement, Refer To Checker Parts Catalog Dated September 1971, Page 5-6, And Checker Service Bulletin No. K-24-72, Pages 1 & 2.												