

ENGINEERING MEMO. #102

TO: Memo. Distribution
 FROM: S. Hori
 SUBJECT: TAIL LAMP REVISION

1. Two additional reflex reflectors will be added to each Tail Lamp Assembly for Models A-12, A-12W, A-12E, A-12W6&8 as soon as possible.
2. The present Tail Lamp Assembly with one reflex reflector will be retained for Models A-11 and A-11E.
3. The Tail Lamp Assemblies will not be interchangeable for service.
4. List of Parts to be affected.

A-11 PART NO.	A-12 PART NO.	NAME
633163	643369	Lamp Assem-Tail (Complete)
633164	643368	Door Assem-Tail Lamp
633165	643370	Door & Panel Assem-Tail Lamp
634045	642728	Door-Tail Lamp
633096(2)	633096(6)	Reflector Assem.
626441(2)	626441(6)	Nut- #10

This revision incorporated on Chassis No. 27992 (other than Aerobus)
 This revision incorporated on Chassis No. 1441 Aerobus