

ENGINEERING MEMO #121

TO: Memo Distribution
 FROM: S. Wilson
 SUBJECT: ACCELERATOR PEDAL MOUNTING

At the request of Management, the accelerator Pedal will be repositioned as soon as possible with a minimum of obsolescence. This revision will require changes in the Front Floor Pan and new Front Floor Mats.

As none of the parts are interchangeable, it will be necessary to change all parts simultaneously.

Special care should be taken to insure accurate records of Chassis Numbers when new parts are incorporated.

<u>PARTS AFFECTED</u>		
OLD NO.	NEW NO.	DESCRIPTION
94569	702784	PLATE-Accelerator Pedal Hinge
95134		PLATE ASSEM-Accelerator Pedal Hinge
95133	701602	PEDAL & PLATE ASSEM-Accelerator
156351	- - -	SCREW-1/4-20 x 2
- - -	271172	NUT & L/W. ASSEM-1/4-20
	SK-2650	INSTALLATION DRWG.-Accel. Pedal (Ref. Only)
640522	Same	PAN-Frt.Floor(Remove 5/8 x 1-3/4 Slot. & Relocate over-Drive Sw. Hole)
634382	Same	MEMBER-Floor Pan Frt. Cross (Remove Square Holes)
633276	- - -	MEMBER & NUT ASSEM-Fl. Pan Frt. Cross
127527	- - -	NUT-1/4-20 Type "C" Clinch (Reduce Usage)
641509	641323	MAT ASSEM-Front Floor (Rubber)
641510	641324	MAT ASSEM-Front Floor(Gray)
641550	641325	MAT ASSEM-Front Floor-Auto. Trans.
641549	641408	MAT ASSEM-Front Floor-Fl. Shift-6 Cyl.
643164	641409	MAT ASSEM-Frt. Floor-Fl. Shift-8 Cyl.
641165	641847	MAT ASSEM-Frt. Floor-Lt. Gray (Limo.)
642321	642085	MAT-Frt. Floor LH-Gray Rubber (Limo.)
642320	642058	JUTE-Frt. Floor Mat (Limo.)
641166	641664	MAT ASSEM-Frt. Floor-Black (Limo.)
642323	642091	MAT-Frt.Floor LH-Black Rubber (Limo.)
- - -	640087	BRKT.-Accelerator Pedal Mtg. New Part
- - -	641406	BRKT. & BOLT ASSEM-Accel. Pedal Mtg. New Part
- - -	626292	BOLT-1/4-20 x 5/8 Ohio Weld #HW-2110 (Increase Usage by (2)