

April 25, 1966

Model B-11E, B-12E

ENGINEERING MEMO #145

TO: Memo Distribution
FROM: R. G. Fuller
SUBJECT: ADJUSTMENT IN REAR AXLE INHIBITOR FOR PREVENTION
OF PROPELLOR SHAFT INTERFERENCE AT THE FLOOR

Only on cars using the 3-1/2" diameter propellor shaft
and standard springs, without helpers:

Replace Inhibitor Bumper #701015 (2) with #92289 (2).

Use nine, each side, of 446477 between the bumper and
the frame bracket and six, each side, above the frame
bracket. This is a total of thirty washers.

The washers will be used as indicated, temporarily, until
spacers can be released and processed.