

March 6, 1967
 Chassis No. Added April 21,
 1967

ENGINEERING MEMO # 174

TO: Memo Distribution

FROM: B. Lewis

SUBJECT: CHANGE IN INSTRUMENT PANEL CLOCK

1. The Model A-12 Instrument Panel Clock part #643161 is no longer available from the vendor.
2. A new clock assembly, part #645228 has been released for production and will require a mounting revision.
3. Effective Point:
This will become effective when present stock of 643161 is exhausted.
4. Old and new clock assemblies will not be interchangeable for Service.
5. List of parts to be affected:

NAME	BUY OR MAKE	OLD PART	NEW PART	I	A	REMARKS
Clock A.-Inst. Panel Comp.	B	643161	645228	No	No	Use W/O Obsoles
Clock A.-Inst. Panel	F	643162	Furn	No	No	Use W/O Obsoles
Socket-Inst. Panel Clock	F	642610	Furn	No	No	Use W/O Obsoles
Nut	F	Furn	Furn	No	No	Use W/O Obsoles
Bulb & Socket-Inst. Panel Clock Lt.	F	----	Furn	No	Yes	New Part
Bulb-2 C.P. 120 S.C. Heavy Duty	B	9417863	----	No	Yes	Reduce Usage
Lockwasher #10 Med. Spring	B	120217	----	No	Yes	Reduce Usage
Panel-Inst. Ctr.-Clock(B-12)	M	642609	Chg. "A & B"	No	No	Rework or Scrap
Panel Inst. Ctr.-Clock(aero)	M	640871	Chg. "B & C"	No	No	Rework or Scrap
Socket & Harness Assem. Clock	B	639256	645232	No	Yes	Rework

This revision incorporated at the following Chassis No.

A-12, A-12W, A-12E - Chassis 46799
 A-12W6, A-12W8 - Chassis 2372