

ENGINEERING MEMO #194

August 14, 1967
Chassis No. Added 4-4-68
Paragraph (2) Rev. 4-9-68
Chassis No. Added 5-9-68
Chassis No. Added 6-3-68
Chassis No. Added 8-16-68

TO: Memo Distribution

FROM: S. Hori

SUBJECT: CHANGE FROM GABRIEL SHOCK ABSORBERS TO MONROE SHOCK ABSORBERS

1. A change will be made as soon as practical from the Gabriel Shock Absorbers to the Monroe Shock Absorbers with a minimum of obsolescence. All shock absorbers will be affected.
2. Due to the difference in ride characteristics of the Monroe and Gabriel Shock Absorbers, it is desirable that the changeover on all Models be made in complete sets of (4). If necessary to reduce obsolescence, unbalanced stock of old parts may be used in pairs only.
3. List of Parts to be Affected:

Name	B or M	Old Part No.	New Part No.	I*	A	Remarks
Shock Abs. A.-Front	B	93959	701964	NO	YES	Service
Shock Abs. A.-Rear	B	93880	701963	NO	YES	Service
Shock Abs. A.-Frt. H.D.	B	95092	701973	NO	YES	Service
Shock Abs. A.-Rear H.D.	B	95091	701974	NO	YES	Service
Shock Abs. A.-Frt. H.D.	B	95710	701965	NO	YES	Service
Shock Abs. A. - Rear	B	95703	701966	NO	YES	Service
Shock Abs. A. - Rear	B	95685	701967	NO	YES	Service
Insulator-Shock Abs.Outer	B	94407	704142	NO	YES	Service

* Interchangeable for service in pairs only.

701964 superseded 93959 on Ch. #80984, Models B-11, B-12, B-12W, B-12E
701963 superseded 93880 on Ch. #81013, Models B-11, B-12, B-12W, B-12E
704142 superseded 94407 on Ch. #81013, Models B-11, B-12, B-12W, B-12E
701965 superseded 95710 on Ch. #8088, Models A-12W6 & 8
704142 superseded 94407 on Ch. #8088, Models A-12W6 & 8
701967 superseded 95685 on Ch. #8104, Model A-12W8
701974 superseded 95091 on Ch. #83019, Models B-11, B-12, B-12E, B-12W