

ENGINEERING MEMO #199

TO: Memo Distribution
 FROM: B. Lewis
 SUBJECT: REAR DOOR PULL HANDLE REVISION

1. In order to update and improve appearance the following change will be made affecting the "Rear Door Pull Handle" used as optional equipment on Checker Models A-11, A-11E and A-12E.
2. Effective as soon as possible but without obsolescence of the present 638082 Handle, a new Handle Assem.-Rear Door Pull part 645414 will be used. This handle change also requires a change in the Rear Door Inner Panels on both 120" and 129" Rear Doors, which must be effective simultaneously with use of the new handle.
3. The new handle is not interchangeable with the old handle nor can it be used to service the old handle because of different mounting requirements. Any surplus of the old handle can be used for service requirements.

List of Parts to be Affected:

NAME	BUY OR MAKE	OLD PART NO.	NEW PART NO.	I	A	REMARKS
Handle A.-Rear Door Pull	B	638082	645414	NO	YES	Use W/O Obsoles.
Screw-1/4-20 x 1 Fill.Hd.	B	-----	148045	NO	YES	New Part
Screw-10-24 x 3/4 Tapp.	B	147840	-----	NO	YES	Service or Scrap
Nut Retainer-#10-24	B	626515	-----	NO	YES	Service or Scrap
B Nut-1/4-20 Pierce	B	626255	-----	NO	YES	Increase Usage
Panel A.-Rear Door Trim(Un-coated)129"WB	M	641835 & 6	Chg."H"	NO	NO	Rework as Req'd
Panel A.-Rear Door Upper Trim 129 WB	B	642173 & 4	Chg."H"	NO	NO	Rework as Req'd
Panel A.-Rear Door Trim (Un-coated)120"WB	M	639321 & 2	Chg."J"	NO	NO	Rework as Req'd

ENGINEERING MEMO #199 (Cont'd)

NAME	BUY OF MAKE	OLD PART NO.	NEW PART NO.	I	A	REMARKS
Panel-Rear Door Trim Uncoated	B	640257 & 8	Chg."N"	NO	NO	Rework as Req'd
Panel A.Rear Door Inner (With Extensions)	M	643993 & 4	Chg."B"	NO	NO	Rework as Req'd
Extension-Rear Door Inner Up- per 129"WB	M	642157	Chg.C,D,E,F	NO	NO	Rework as Req'd
Extension&Nut A. Rear Door Inner Up.129"WD	M	-----	645337	NO	YES	New Part
Panel-Rear Door Inner	M	640143 & 4	Chg."R"	NO	NO	Rework as Req'd
Panel A.Rear Dr.Trimmed Cab	M	639311 & 12	Chg."D"	YES	NO	Rework as Req'd
Panel-Rear Quarter Trim	B	640263 & 4	Chg."H"	NO	YES	Rework

645414 replaced 638082 on Chassis #81738, Models A-11,A-11E,A-12E