

July 1, 1968
 "A" Revisions 7-22-68
 "B" Revisions 8-13-68

ENGINEERING MEMO #230

TO: Memo Distribution
 FROM: J. Stockwell
 SUBJECT: HOOD INSULATION RETAINERS

Part Description	Material	Part Number	Change	NO	NO	Action
Reinf.-Hood Rear Outer	M	630337 630338	Chng. "D"	NO	NO	Rework
Brace-Hood-Upper	M	634225	Chng. "A"	NO	NO	Rework
Brace-Hood-Lower	M	634226	Chng. "A"	NO	NO	Rework
Wire-Hood Insul.Ret. Prt.	M		644501	NO	YES	New Part
Wire-Hood Insul.Ret. Pr.	M		644522	NO	YES	New Part
Brkt-Hood Insul.Ret.-Wire	M	-----	644551	NO	YES	New Part
Wire-Hood Insul.Ret.	M	-----	644552	NO	YES	Increase New Part Usage
Clip-Wire & Tubes Med	B	626797	Chng. "A"	NO	YES	Increase Usage
Hood A.Comp.Less Med	M	641476	Chg. "A" & "B"	YES	YES	Rework

Not to be Used