

August 8, 1968
Note Added 8-15-68

ENGINEERING MEMO #236

TO: Memo Distribution
FROM: B. Lewis
SUBJECT: WINDSHIELD WIPER REVISION

Effective on all models as soon as available and with a minimum of obsolescence of cancelled parts the following revisions will be made:

- A. The present LH & RH Pivot Body and Connector Assemblies and the LH Wiper Arm Assembly will be cancelled and replaced by new parts designed to give more quiet operation and longer service life. Old and new design are interchangeable only when used in combination and must not be intermixed either in production or during service replacement. Present stock of cancelled parts should be used without obsolescence in balanced quantity only and any out of balance surplus held for service.

D. List of Parts to be Affected:

| ITEM | PART NAME | B or M | OLD PART NUMBER | NEW PART NUMBER | I | A | REMARKS |
|------|---|--------------|-----------------------|-----------------------|----|----|--------------------------------------|
| 1. | Arm Assem.-Windshield Wiper Blade-LH | B | 645519 | 645797 | NO | NO | Use W/O Obsoles. in Bal.Quan.Only |
| 2. | Pivot, Conn.Arm & Disc Assem.-LH | B | 645517 | 645795 | NO | NO | Use W/O Obsoles. in Bal.Quan.Only |
| 3. | Pivot & Conn.Arm Assem.-RH | B | 645518 | 645796 | NO | NO | Use W/O Obsoles. in Bal.Quan.Only |

NOTE: Vendor Part Number will not change for above new parts, necessitating special care on the part of Receiving and Production Departments to properly identify the new parts which the Vendor identifies as Change "A" of the original part number.