

ENGINEERING MEMO #334

TO: Memo Distribution  
 FROM: C. Bland  
 SUBJECT: BODY SIDE MOLDINGS

At the request of management the present metal molding will be replaced with an adhesive backed extruded vinyl molding.

This change will be made with a minimum of obsolescence of the present molding

Service will be affected in that old and new parts are not interchangeable.

Following is a complete list of the parts to be affected.

ITEM	NAME	B O F M	OLD PART NUMBER	NEW PART NUMBER	INT. NEW FOR OLD	AVAIL. FOR AFTER CHG.	REMARKS
1.	Molding-Rr.Dr.Side 129WB	B	642205	646669	NO	NO	Serv.or Scrap
2.	Molding-Frt.Door Side	B	640414	646666	NO	NO	Serv.or Scrap
3.	Molding-Rear Door Side	B	640389	646667	NO	NO	Serv.or Scrap
4.	Ret.A.-Body Side Molding	B	626594	-----	-	YES	Reduce Usage
5.	Ret.A.-Side Molding	B	626488	-----	-	NO	Serv.or Scrap
6.	Nut & Sealer A.-#10-24	B	626489	-----	-	YES	Reduce Usage
Ⓐ 7.	Molding-Ctr.Dr.Side	B	640731	646667	NO	NO	Serv.or Scrap
8.	Inst.-Molding Trim Holes	M	649281	-----	-	YES	Ref.Drawing
9.	Inst.-Molding Side	M	649310	-----	-	YES	Ref.Drawing
10.	Molding-Front Fender	B	-----	646665	NO	YES	New Part
11.	Molding-Rear Fender	B	-----	646668	NO	YES	New Part
Ⓐ 12.	Install.-Body Side Mldg.	R E F	-----	649483	-	YES	Ref.Drawing
Ⓐ 13.	Install.-Body Side Mldg. 189 WB	R E F	-----	649484	-	YES	Ref.Drawing

This Memo incorporated @ Ch.#35708 P.O.#4877