

May 5, 1975

ENGINEERING MEMO #364

TO: Memo Distribution
FROM: C. Bland
SUBJECT: REVISED LOCK SETS FOR 1976 MODEL YEAR.

The lock set vendor has requested that Checker Motors assign new part numbers to Lock Sets, Lock Cylinder Assemblies and Keys for 1976 production to reflect a General Motors change in the key section for both Primary and Secondary Locks.

The new Lock Sets can supersede the old sets without obsolescence in production, but the changeover should be scheduled to coincide with the October 1, 1975 start of the 1976 model year production.

Service will be affected in that old and new keys and lock cylinders will not interchange because of revised key grooves. Key code number series will also change on the new locks and coding sheets will be furnished to service at a later date.

Following is a complete list of the parts affected:

ITEM	NAME	B or M	OLD PART NUMBER	NEW PART NUMBER	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS
1	Lock Set-Gl Box & Doors	B	651895	651981	YES	YES	Use W/O Obs
2	Lock Set-Drs Deck Lid & Gl Box	B	651896	651982	YES	YES	Use W/O Obs
3	Lock Set-Drs Dk Lid & Gl Box Keyed Alike	B	651897	651983	YES	YES	Use W/O Obs
4	Lock Set-Ignition	B	651898	651984	YES	YES	Use W/O Obs
5	Lock Set-Ign Keyed Alike	B	651899	651985	YES	YES	Use W/O Obs
6	Lock Set-Drs Dk Lid & Gl Box Complete	M	651900	651986	YES	YES	Use W/O Obs
7	Lock Set-Drs Dk Lid & Gl Box Complete Keyed Alike	M	651901	651987	YES	YES	Use W/O Obs
8	Lock Set-Dr & Gl Box Complete	M	651911	651988	YES	YES	Use W/O Obs
	Lock Cyl Asm-Door	F	651902	651989	NO	YES	Serv or Scrap Unbal Stock