

ENGINEERING MEMO #365

June 4, 1975  
 Rev: 8-19-75  
 Items(13,14)Added  
 12-11-75;"A"Chg 12-29-75;

TO: Memo Distribution  
 FROM: C. Bland  
 SUBJECT: PRODUCT IMPROVEMENT

The following areas have been revised for product improvement and cost reduction.

1. Courtesy Light Switch incorporated into the Head Lamp Switch.
2. Seat Belt Warning Harness incorporated into the Instrument Panel Harness.
3. Removing a charging circuit in the Instrument Panel Harness.

The following is a complete list of parts to be affected.

ITEM	NAME	B or M	OLD PART NUMBER	NEW PART NUMBER	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS
1	Harness Asm Inst Dash Wrng	B	651936	651997	No	Yes	Serv.or Scrap
2	Harn & Jpr Asm-Inst Dash Wrng	M	651960	- - -	-	Yes	Serv.or Scrap
3	Harn-St Belt Wiring(Jumper)	B	651938	- - -	-	Yes	Serv.or Scrap
4	Sw Asm-P/P & Rotary Hd Lamp	B	93814	651999	Yes	Yes	Serv.or Scrap
5	Harness Asm-Main Engine	B	705595	705731	No	Yes	Serv.or Scrap
6	Harness Asm-Fwd Lamps	B	705070	705732	No	Yes	Serv.or Scrap
7	Sw Asm-Courtesy Light	B	626942	- - -	-	Yes	Reduce Usage
8	Adapter-Courtesy Lamp Sw	M	651998	- - -	-	Yes	Reduce Usage
9	Wire #14 Ga Auto Stranded-Red	B	MD-127	- - -	-	-	Revise Usage
10	Tubing-9/64 ID Neoprene	B	MQ-107	- - -	-	-	Revise Usage
11	Terminal-15 Amp Female Snap	B	80310	- - -	-	-	Revise Usage
12	Terminal-Male Blade	B	626943	- - -	-	-	Revise Usage
13	Screw #8-32 x 1/2 RHCR Type "C" Tapp	B	147671	- - -	-	-	Revise Usage
14	Tape-Scotch 3/4" Wide Elec	B	MA-138	- - -	-	-	Revise Usage