

February 3, 1976

ENGINEERING MEMO #368

TO: Memo Distribution
 FROM: C. Bland
 SUBJECT: AIR TRANSFER DUCTING.

The present vendor, because of manufacturing environmental problems, has requested Checker Motors to change from the wire inserted rubberized cloth construction to a wire inserted, E.P.D.M., plastic construction.

This change will be made with a minimum of obsolescence.

Following is a complete list of the parts to be affected.

ITEM	NAME	B or M	OLD PART NUMBER	NEW PART NUMBER	NEW FOR OLD	AVAIL AFTER CHG	REMARKS
1	Duct A.-Fresh Air Intake	B	637195	653109	Yes	No	Use w/o Obs
2	Clamp A.-4 1/4 Type "D" Hose	B	451246	- - -	-	Yes	Serv or Scrap
3	Clamp A.-4.38 Type "D" Hose	B	- - -	9422753	-	Yes	New Part
4	Duct & Hose Asm-Def	M	639232	Chg"C"	Yes	No	Use w/o Obs
5	Hose A.-Defroster	B	640232	653110	Yes	No	Use w/o Obs
6	Duct A.-Rear A/C LH	B	651591	653111	Yes	No	Use w/o Obs
7	Duct A.-Rear A/C RH	B	651592	653112	Yes	No	Use w/o Obs
8	Rivet-3/16 AD 66 BS LF Pop	B	626790	- - -	-	Yes	Increase Usage