

ENGINEERING MEMO #369

TO: Memo Distribution  
 FROM: C. Bland  
 SUBJECT: INSIDE REAR VIEW MIRROR.

The present vendor of CMC inside rear view mirrors have discontinued making this type of mirror.

The new mirror will be mounted to the windshield glass.

This change will affect service in that old style mirrors will not be available after the change. The new style mirror can be used to service old by installing the mirror to the windshield glass as shown on G.I. 240 D-1 with Loctite Minute-Bond Adhesive 312, Catalog No. 33-33.

This change will be made with a minimum of obsolescence.

Following is a complete list of parts affected.

ITEM	NAME	B or M	OLD PART NUMBER	NEW PART NUMBER	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS
	Pnl & Nut A.-W/S Opg Top	M	645511	653121	Yes	No	Rework
2	Pnl-W/S Opg Inr Fr Top	M	644381	646928	Yes	No	Rework
3	Nut-#8-32 Type C Clinch	B	127615	- - -	-	Yes	Reduce Usage
4	Mirror A.-Inside Rr View	B	645573	653122	No	No	Serv or Scrap
5	Bracket-Rr View Mirror	M	644400	- - -	-	Yes	Serv or Scrap
6	Mirror A.-Day/Night	B	645574	653122	No	No	Serv or Scrap
7	Glass-W/Shield Clear	B	646746	653123	Yes	Yes	Rework
8	Glass-W/S Tinted	B	646747	653124	Yes	Yes	Rework
9	Cowl & W/S Opg Fr A	M'	651711	Chg"B"	Yes	No	Rework

ENGINEERING MEMO # 369 (Cont'd.)

ITEM	NAME	B or M	OLD PART NUMBER	NEW PART NUMBER	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS
10	Scr #8-32 x 1/2 OHCR Mach Hdr Pt	B	187871	- - -	-	-	Revise Usage
11	Nut-5/16-24 Hex GM 286M	F	124921	- - -	-	-	Serv or Scrap
12	Scr #6-32 x 1/2 OHCR Mach Chrome Brt	F	156655	- - -	-	-	Serv or Scrap
13	Mirror A. Inside Rr View	F	645579	- - -	-	-	Serv or Scrap
14	Bezel-Mirror Protective	F	644425	- - -	-	-	Serv or Scrap
15	Stud Ball-Inside Rr View Mirr	F	644424	- - -	-	-	Serv or Scrap
16	Spring-Rr View Mirror Pivot Ball Tension	F	644411	- - -	-	-	Serv or Scrap