

June 11, 1979

ENGINEERING MEMO #408

TO: Memo Distribution

FROM: C. Bland

SUBJECT: SEAT BELT SWITCH CHANGE REQUESTED BY THE VENDOR.

The present switch N.O. (normally open) has been replaced with a N.C. (normally closed) by the Vendor.

This change will be made with a minimum of obsolescence.

Service will be affected in that old and new are not interchangeable.

Following is a complete list of parts to be affected.

REVISIONS			
DATE	ITEM REV & PAGE NO.	DATE	ITEM REV & PAGE NO.
10-24-79	Rev P.2		
10-29-79	Rev P.2		

ENGINEERING MEMO # 408 (Cont'd)

ITEM	NAME	B OR M	OLD PART NUMBER	NEW PART NUMBER	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS
1	Harness A.-Inst Dash Wiring	B	653439	653515	NO	NO	Use W/O Obs
(B)2	Harness A.-Frt Seat LH	B	653195	653517	NO	NO	<del>Use W/O Obs</del> Serv or Scrap
(B)(A)3	<del>Relay A. Horn &amp; Buzzer</del>	B	703557			YES	Reinstate
(A)4	<del>Relay A. Horn</del>	B		653484		YES	New Part Cancelled
(B)5	<del>Buzzer Asm Warning</del>	B	653300			YES	Increase Usage