

October 9, 1980

ENGINEERING MEMO #423

TO: Memo Distribution
FROM: C. Bland
SUBJECT: INSIDE HOOD LATCH RELEASE (EFFECTIVE APPROXIMATELY
March 2, 1981)

At management's request, the outside Hood Latch Release will be replaced with an Inside Release.

The change will be made with a minimum of obsolescence.

Following is a complete list of parts to be affected:

REVISIONS			
DATE	ITEM REV & PAGE NO.	DATE	ITEM REV & PAGE NO.
12-19-80	Items 11-13 Added		
1-27-81	Item 14 Added		
2-10-81	Items 15-16 Added		
2-13-81	Effective Date Chg P.1		

ITEM	DESCRIPTION (New Parts Only)	B OF M	OLD PART NUMBER	B OF M	NEW PART NUMBER	FOR DEPT USE ONLY	INT NEW FOR OLD	AVAIL AFTER CHG	REMARKS (Old Parts Only)
1	Cont A.-Hood Lat Rel.	-	-	B	653607		-	YES	New Part
2	Bracket-Hood Lat Rel. Cont. MT	-	-	M	648280		-	YES	" "
3	Panel-Dash	M	646026		Chg. Z		-		Rework
4	Liner Asm - Dash	B	645966		Chg. M		-		Rework
5	Release Asm.-Hood Lock	M	653329	-	-		-	NO	Serv. or Scrap
6	Brkt-Hood Lock Rel. Lever	M	648201	-	-		-	NO	Serv. or Scrap
7	Lever-Hood Lbck Rel.	M	648202	-	-		-	NO	Serv. or Scrap
8	Wire-Hood Lock Rel.	B	648203	-	-		-	NO	Serv. or Scrap
9	Rivet-T/G Support Shldr.	B	536175	-	-		-	NO	Serv. or Scrap
10	Washer-Wave	B	526356	-	-		-	YES	Revise Usage
11	SCR-#10x1 P.H. C.R. Type A Tap	B	161909	-	- - -		-	-	Increase Usage
12	Control & Supt Asm-Park Brk	M	707668	-	Chg B		YES	YES	Rework
13	Brkt Asm-Hood Latch Rel Cont Mt	-	- - -	M	653608		-	-	New Part
14	Plate & Lock Asm-Hood	M	653327	-	Chg B		NO	NO	Rework
15	Supt-Park Brake	-	- - -	M	708655		-	-	New Part
16	Control Asm-Park Brake	B	705055	B	707658		YES	NO	Use w/O Obs