



INCLUDED LEG HARDWARE:



1. Place table top upside down on clean surface.



2. Line up holes at top of V-Leg with holes on underside of table top . Make sure leg is angle outward.



3. Secure leg to top with wood screw .

OFFICESOURCE.COM