

Raven Marine Service Bulletin

June 10, 2011

Austin Technology Center

14000 Summit Drive, Suite 700
Austin, TX 78728-7109
Voice: +1 (800) 460-2167
Fax: +1 (512) 238-1135



Sioux Falls Office

1814 F Avenue
Sioux Falls, SD 57117-5107
Voice: +1 (800) 331-3500
Fax: +1 (605) 331-3520

Incorrect storage may damage your Bluetooth Pilot Interface (BPI) or cable. Before stowing the BPI, disconnect all cables from the BPI. Do not wind the cable around the BPI to store it.



Raven Marine is committed to supporting professional ship pilots through annual recertification of our systems and routine, ongoing support, including replacement parts sales, software updates, service bulletins, and one-on-one support through e-mail and telephone. Thank you for your business.

-The Raven Marine Team-