

Raven Marine Service Bulletin

No Position After Cycling Receiver Power

If you cycle the power on the Raven or third-party GPS receiver without re-starting the Raven software, sometimes WHII will report '**NO POS**' and SendClient will report '**Position data not available**' without ever recovering a position. (The messages shown below are normal unless they last longer than 1 minute.)

To recover, you must exit and re-start WHII. We thought that SendClient 4.74 might correct this problem, but we have observed the problem in SendClient 4.74. A solution will be forth-coming, but, due to the need for beta test cycles, the solution will not appear until after the primary release on June 2, 2010.

