

Globe Dec 4, 1908 Pembroke  
Head-on collision at Pembroke  
Engineer Fred Rowe killed.

The eastbound passenger train met the locomotive going west, both travelling at forty miles per hour. The engines meeting with a tremendous crash leaped into the air and sank completely demolished in a big heap of ruins.

This is another wreck due to carelessness. The eastbound engine was running wild and disregarding the order to wait at Graham station for the passenger train to pass, took chances on reaching Pembroke in safety.