
Diesel Emissions Service

RETROFIT AND REPOWER SPECIALISTS

Portland | Redding | Oakland | Ontario



DES VM6050 HUG R50 VERTICAL MOUNT

ALL INSTALLATION INSTRUCTIONS AND GUIDELINES MUST BE THOROUGHLY READ AND UNDERSTOOD BEFORE INSTALLING A DIESEL EMISSIONS SERVICE PRODUCT



PRODUCT GUIDLINES

Diesel Emissions Service recommends its products be installed by a trained technician with proper tools and safety equipment. In addition all Diesel Emissions Service mounting brackets should be installed using good judgment and sound mechanical principles. Since all installations are unique, it is the sole responsibility of the installer to determine the best fit and function of the DPF mounting brackets.


PRODUCT SAFETY


Diesel Emissions Service products are designed for "ON-ROAD" applications only. Modifications to any Diesel Emissions Service product are not recommended and can compromise the bracket performance. Diesel Emissions Service claims no liability or responsibility for the improper application or installation of its products.


PRODUCT WARRANTY

Diesel Emissions Service warrants to the original purchaser of its products that such products will be free from defects in material and workmanship under normal use. Diesel Emissions Service's obligation under this warranty is solely and exclusively limited to repair and or replacement, at Diesel Emissions Service option, of the product (or components thereof) which Diesel Emissions Service's examination proves to its satisfaction to be defective. Diesel Emissions Service SHALL HAVE NO OBLIGATION FOR CONSEQUENTIAL DAMAGES TO PERSONAL OR REAL PROPERTY. OR FOR INJURY TO ANY PERSON.


This warranty does not apply to products which have been subject to improper use, accident, negligence, abuse or misuse.








CORRECT



CROSS BAR(6) MUST BE PLACED PARALLEL TO 56"VERTICAL STANCHION(3)





FAILURE TO INSTALL CROSS BAR (6) PARALLEL TO VERTICAL STANCHION (3) CAN COMPROMISE BRACKET INTEGRITY AND RESULT IN BRACKET FAILURE AND OR DAMAGE TO FILTER!

DIESEL EMISSIONS SERVICE

PORTLAND REDDING OAKLAND ONTARIO 888-792-2922

Drawing No.

DES VM6050

Scale NOT TO SCALE


e A

Sheet 4 OF

ITEM	QTY	COMPONENT DESCRIPTION
3	1	56" VERTICAL STANCHION
6	1	CROSS BAR

CORRECT (5) (6⁾ ISOLATORS (D) MUST BE **COMPRESSED EQUALLY** ISOLATORS (D) SHOULD BE COMPRESSED APPROXIMATELY

INCORRECT



IMPROPER ISOLATOR COMPRESSION CAN LEAD TO ISOLATOR AND **BRACKET FAILURE**

Drawing No.

DIESEL EMISSIONS SERVICE

PORTLAND REDDING OAKLAND ONTARIO 888-792-2922


ITEM QTY COMPONENT DESCRIPTION QTY ITEM HARDWARE DESCRIPTION UPPER ISOLATOR BRACKET 4 UPPER CROSS BAR BRACKET 2" THICK POLY ISOLATORS 5 D 4 CROSS BAR

25-30%

DES VM6050


Scale NOT TO SCALE Slze

CORRECT



LOWER CROSS BAR BRACKET (7) MUST SEAT FLUSH TO FRAME RAIL

INCORRECT





NEVER SPACE LOWER CROSS BAR BRACKET (7) AWAY FROM FRAME RAIL

DIESEL EMISSIONS SERVICE

PORTLAND REDDING OAKLAND ONTARIO 888-792-2922

Drawing No.

DES VM6050

Scale NOT TO SCALE Size A Sheet

ITEM	QTY	COMPONENT DESCRIPTION	ITEM	QTY	HARDWARE DESCRIPTION
7	1	LOWER CROSS BAR BRACKET	F	8	1/2 - 13 X1-3/4 BOLT,NUT,WASHER,ASSY

