

Geomagic Hexagon Absolute SI Plugin 1.0

Release Notes version A, February 21, 2011

Enables Geomagic **Studio 12** and Geomagic **Qualify 12** and *subsequent releases* to operate with the Hexagon Absolute SI scanner on Microsoft XP, Vista, and Windows 7.

Technical Support

Geomagic, Inc.
P.O. Box 12219
Research Triangle Park, NC 27709 USA
Phone: +1 (800) 251-551 or +1 (919) 474-0122
Toll-free in the USA: (800) 251-5551
Fax: +1 (919) 474-0216
Asia: +86.21.6432.0776
Europe: +36.1.789.3436

Web Sites

Geomagic, Inc. <http://www.geomagic.com>
Technical Support <http://support.geomagic.com>
Training <http://training.geomagic.com>

Email Addresses

Technical Support support@geomagic.com
Training training@geomagic.com
Services servicesinfo@geomagic.com
Licensing ops@geomagic.com

Prerequisites

This plugin requires a Geomagic product listed in the heading. To verify your current version, launch the application and select **App Button > About**. The text box indicates the current software version.

This plugin supports the 32-bit version of Microsoft Windows XP, Vista, and Windows 7. If running on a 64-bit version of Windows, users will need to install the 32-bit version of the Geomagic application and run the plugin in 32 bit mode.

These additional applications are required to operate the Hexagon Absolute plugin 1.0:

- WinRDS 3.0 or later

Installation

1. Verify that the cable connections between the equipment and the PC.
2. Verify installation of Geomagic product listed in the heading.
3. Log in to Windows as a user with administrative privileges.
4. Obtain and install WinRDS 3.0

5. Obtain and install the Hexagon Absolute SI installer named from [Geomagic Support and Download Website](#).
6. Reboot the computer.