

Geomagic Konica-Minolta Range7 Plugin 2.0

Release Notes version C, May 28, 2010

Enables Geomagic **Studio 12** and **Geomagic Qualify 12**
to operate with Konica Minolta Range 7

Technical Support

Geomagic, Inc.
P.O. Box 12219
Research Triangle Park, NC 27709 USA
Phone: +1 (800) 251-551 or +1 (919) 474-0122
Toll-free in the USA: (800) 251-5551
Fax: +1 (919) 474-0216
Asia: +86.21.6432.0776
Europe:+36.1.789.3436

Web Sites

Geomagic, Inc. <http://www.geomagic.com>
Technical Support <http://support.geomagic.com>
Training <http://training.geomagic.com>

Email Addresses

Technical Support support@geomagic.com
Training training@geomagic.com
Services servicesinfo@geomagic.com
Licensing ops@geomagic.com

Prerequisites

This plugin requires the Konica-Minolta Range Viewer software 1.33.

This plugin requires a Geomagic product listed in the heading. To verify your current version, launch the application and select **App Button > About**. The text box indicates the current software version.

Compatible with only the 64-bit versions of Windows XP and Windows Vista.

Installation

1. Verify installation of a Geomagic product listed in the heading.
2. Log in to Windows as a user with administrative privileges.
3. Verify installation of the newest drivers that come with the Minolta equipment.
4. Download the setup program from the [Plugins Page](#) of the Geomagic Support web site.
5. Run the installer.
6. Follow other on-screen prompts and click **Finish** when installation is complete.
7. Start the Geomagic application and verify that Konica-Minolta appears in the **Hardware** tab.

User Instructions

1. Launch Konica-Minolta's Range Viewer and complete the scanning process.
2. Launch the Geomagic application.
3. Choose **Hardware > Konica-Minolta Range7 Plug-In**.
4. Click **Connect**.
5. In the Range Viewer software, change to the Edit mode tab and click the **Export Elements to Other Applications** icon on the left toolbar to send the data to the Geomagic application.