

Geomagic NDI OPTOTRAK PROseries Probing Plugin 2.0

Release Notes (v2.0.3), January 27, 2012

This plug-in enables Geomagic Studio 2012, Geomagic Qualify 2012, Geomagic Qualify Probe 2012, or Geomagic Wrap 2012 to interface with the NDI OPTOTRAK PROseries.

Technical Support

Geomagic, Inc.
430 Davis Dr. Suite 300
Morrisville, NC 27560 USA

Phone: 919-474-3036
Toll-free in the USA: 800-251-5551
Fax: 919-474-0216

China: +86 21 6432 0776
Japan: +81 90 8496 9846
Europe: +49 (0) 711 71 91 7890

Web Sites


Geomagic, Inc. <http://www.geomagic.com>
Technical Support <http://support.geomagic.com>
Training <http://training.geomagic.com>

Email Addresses

Technical Support support@geomagic.com
Training traininginfo@geomagic.com
Licensing/Sales ops@geomagic.com
Marketing marketinginfo@geomagic.com

Prerequisites


The following prerequisites must be verified prior to installing the plugin:

- **Geomagic Software Version:** This plugin requires a Geomagic product listed in the heading above.
To verify your current version, launch the application and select **App Button**  **> About**. The About dialog box displays the current software version (2012.X.X).
- **Supported Operating Systems:** This plugin supports the 32-bit and 64-bit versions of Microsoft Windows XP and Windows 7. Windows Vista is *not* supported.
- **Additional Software:** The NDI ToolTray software must be installed and running.

Installation

1. Verify the installation of the supported Geomagic product (as listed above).
2. If necessary, log in to your system as a user with administrative privileges.
3. Verify that the NDI ToolTray software is installed and running on your system.

For more information, contact your local systems administrator.

4. From the [Plugins Page](#) of the [Geomagic Support](#) web site, download the plugin installer (**NDIOptotrak20_32.exe** or **NDIOptotrak20_64.exe**). Be sure to download the correct bit version (32-bit or 64-bit) for your system.
5. Run the plugin installer (**NDIOptotrak20_32.exe** or **NDIOptotrak20_64.exe**).
6. Reboot your system.
7. Start the Geomagic application and verify that the plug-in appears in the **Hard Probing Plug-In** drop-down list under **App Button**  **> Options > Hardware > Digitizers**.

Known Issues

None