

Geomagic NDI VicraSCAN Plugin 1.0

Release Notes Version A, October 23, 2012

This plug-in allows users of Studio, Qualify, or Wrap 2012 to interface with the NDI VicraSCAN on Microsoft XP and Windows 7 (32-bit and 64-bit). The user is able to scan using optical targets directly in Geomagic products using the NDI VicraSCAN.

Technical Support

Geomagic, Inc.
P.O. Box 12219
Research Triangle Park, NC 27709 USA
Phone: +1 (800) 251-551 or +1 (919) 474-0122
Toll-free in the USA: (800) 251-5551
Fax: +1 (919) 474-0216
Asia: +86.21.6432.0776
Europe:+36.1.789.3436

Web Sites

Geomagic, Inc. <http://www.geomagic.com>
Technical Support <http://support.geomagic.com>
Training <http://training.geomagic.com>

Email Addresses

Technical Support support@geomagic.com
Training training@geomagic.com
Services servicesinfo@geomagic.com
Licensing ops@geomagic.com

Prerequisites

This plugin requires a Geomagic product listed in the heading. To verify your current version, launch the application and select **App Button > About**. The text box indicates the current software version.

This plug-in requires a manufacturer driver called NDI Scan. It's available at NDI's support site: <https://support.ndigital.com/>. The site is password protected; VicraSCAN users will need to have an existing account to download the driver.

To communicate with NDI Scan, the plug-in must open a TCP/IP port. If Windows has restrictive firewall settings, it will block the connection. Users should unblock Qualify/Studio following this procedure: <http://www.technipages.com/blockunblock-programs-in-windows-firewall.html>

This plugin supports the 32-bit and 64-bit version of Microsoft Windows XP and Windows 7.

Installation

1. Download the file.
2. Install the plugin by double-clicking the downloaded file.
3. Install the manufacturer driver, NDI Scan, from NDI's support site <https://support.ndigital.com/>
4. Reboot the computer.
5. Start Geomagic Studio 2012, Wrap 2012, or Geomagic Qualify 2012.