Assembly Instruction Sheet #S-1054 P31 For Style 1054P31

A. Pass the supply when through the Crossbar (EE). Aftech the Crossbar (EE) to the Outlet Box (OC) with the head of the Green Ground Screw facing you. Secure it with Outlet Box Screwe (not included). Tighten until snug.

A. Lies standard wire connectors (not included) to make all wire connections. Twist connections until wires are signity joined together. Wrap sech connection with approved electrical tips and carefully staff all the connection when into the Outlet Box.

STEP 3 - Attach Cross

ber to Quillet Box

STEP 5 - Wine Co

a Required: Flathead screwictiver, Phillips screwictiver, plient, wire outlient, wire sirippent, electrical tupe, safety glasses. Source: (19) 1207 LED YSRV DIMINABLE (2000K) Source: (19) 1207 LED YSRV DIMINABLE (2000K) serificit: Identify and happed all parts before beginning installation. Check package content led and diagrams below to be sure all parts are and. If any parts are missing or damaged, do not ellempt to assemble, install, or operate the Sidure. Context customer service for replacement

△Warnings and Cautions

Turn off electricity at circuit breaker or main fuse box before installation. Consult a licensed electricism if in doubt. These instructions are provided for your safety. It is very important you read them completely before installing the thiure. We strongly recommend that a licensed, professional electricism perform the installation.

Disconnect fidure from power source before replacing bulbs. Make sure bulbs are given sufficient time to cool before removal.

Package Contents A Footure Body x1 (Step 1 Continued

Hardware Contents DESCRIPTION QUANTITY

Outlet Box Sore

STEP 1 - Inetail Support Arm.

A.Stuff the wire into the Arms, then heart the Arms into the holes on the Floture Body accordingly figether then tigether

A. Line up a set of holes on the STEP 2 - Attach Mounting Screws, Lock Washers and Hex Nuts to Crossbar . on the ceiling carnopy.

Thread Mounting Screws (DD) Focuse Boo Crossbar (EE) and Holes into the holes on the Washers and thread Hex Nuts onto the Mounting ber (EE). Pass Lock Figure 1 Lock Son

STEP 4 — Fit Ceilling Canopy to Grossbar Assembly

A. Fit the ceiling canopy to Mounting Screws (DD) and secure
with Decorative Cape(AA), Note: The ceiling canopy should
be stug against the ceiling and the Decorative Cape(AA).
If not, adjust the length of the Mounting Screws (DD) by
unscrewing the Hax Nut and Lock Washer and then
acrewing Mounting Screws (DD) in or out of the Crossbar
(EE) until the correct length is achieved. Once the ceiling
canopy is secure, remove the Decorative Cape (AA) and
ceiling canopy and proceed to Step 5.

Outlet Box Screws Ground Wire

from outlet box Bare, or Green from outlet bar

Green Ground Screw on the Crossber

from fixture Ground wire

Ground wire

Supply Wires with

Ŕ

Ė

Bare, or Green Ground wire

Ground wire from fluture

Outlet Box


cullet box (or Rec Black wire from

> from fixture Black wire

White wire from outlet bax

White wire from focure

STEP 6 - Install Calling Canopy to Callin A Carofully tuck all wires Carefully tuck all whree into the outlet box and position the ceiling canopy of the Fbdure Body (A) over the outlet box. Align the holes in the ceiling canopy with the Mounting Gune Bran neithfül ve (DD). Secure with Decorative Cape (AA) and hand Figure 6



≱

tand tighten until anug.

Figure 2

Figure 6