

Product Safety Recall

↗ DOMETIC RV Refrigerators, RUA6 & RUA8 series

Models affected / Description

RUA6408X / 2-door refrigerator, absorption, 188 L

RUA8408X / 2-door refrigerator, absorption, 224 L

Sold in various brand RV's & caravans: July 2018 to Dec 2020

Affected serial number ranges:

MB 82200938 to MB 85100130

MB 90200892 to MB 95200685

MB 00100565 to MB 03701182



Defect

A small wiring loom may overheat and char when the product is running on 12V DC.

Hazards

In the unlikely event that overheating/charring occurs, and there is also foreign combustible material in the vicinity behind the refrigerator, it could lead to a fire.

What to do

If you have one of the above refrigerator models in your RV or caravan, check the serial number on the rating label located inside to the left. If your S/No falls within one of the ranges above, **stop using the product on settings AUTO or  immediately**, and contact Dometic to arrange for fitment of a replacement wiring loom free of charge.

NOTE: it is perfectly safe to continue using the product (when parked) on either gas or AC. Select either  (gas) or  (AC) with the control knob.

Do not select AUTO or

Contact details

Visit dometicrecall.com.au, or call 1800 21 21 21 (Mon-Fri 8 am - 5 pm EST), or email qldservice@dometic.com.au

See productsafety.gov.au for
Australian product recall information