



After right-clicking on a surface of a step model if you find this icon then the surface is a planer surface





Here, the icon for making a sketch does not appear means the selected surface is not a planer surface.