


Moldy Attic

THE PROBLEM



Mold in your attic is not normal, not healthy, and a sign that there is another problem in your home causing the relative humidity in your attic to go above 75% so mold can grow on wood and insulation. Dr. Energy Saver can surely fix the relative humidity problem with other solutions, but what about the mold that's already there? Can it be eliminated with an effective treatment?

Result - Mold all over your roof deck, odor and even rot.



DR. ENERGY SAVER® SOLUTION

Mold-X2 and **Mold-X2** *Cleaner* *Botanical*



Mold-X2 Cleaner effectively eliminates mold and mildew stains on contact. It is non-abrasive and non-flammable, and is sprayed on effected areas. There is a temporary odor from the product, so we recommend that homeowners leave the house for a few hours, depending on how well the space can be ventilated. Once Mold-X2 Cleaner is applied, mold disappears instantly, leaving wood surfaces looking nearly new. Mold-X2 Botanical, a plant-based disinfectant with a pleasant, temporary scent, is sprayed or fogged on surfaces, which prevents mold from growing back. Now your attic is ready for other Dr. Energy Saver solutions.

Result - Mold eliminated, no odors or wood rot.

Unit of Measure - Sq. ft. of roof deck.

 Watch our "On the Job" video:
www.drenergysavervideos.com/A1-5