SAFETY DATA SHEET



1. Identification

Product identifier Behr Premium Aerosol - Black - Satin

Other means of identification

Product code B006944

Recommended use Architectural Coating

Recommended restrictions None known.

Manufacturer/Importer/Supplier/Distributor information

Supplier Behr Process Canada, Ltd.

2750 Centre Avenue N.E.

Calgary, AB T2A 2L3

Emergency telephone (US)+1 760 476 3962

(US)+1 866 519 4752

Access code 335213

2. Hazard identification

Physical hazards Flammable aerosols Category 1

Gases under pressure Liquefied gas

Health hazards Serious eye damage/eye irritation Category 2A

Sensitization, skin Category 1
Carcinogenicity Category 1B
Reproductive toxicity (the unborn child) Category 2

Specific target organ toxicity following single Category 3 narcotic effects

exposure

Label elements



Signal word Danger

Hazard statement Extremely flammable aerosol. Contains gas under pressure; may explode if heated. May cause an

allergic skin reaction. Causes serious eye irritation. May cause drowsiness or dizziness. May

cause cancer. Suspected of damaging the unborn child.

Precautionary statement

Prevention

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Do not spray on an open flame or other ignition source. Keep container tightly closed. Ground and bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting equipment. Use non-sparking tools. Take action to prevent static discharges. Do not pierce or burn, even after use. Avoid breathing mist/vapours. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves/protective clothing/eye

protection/face protection.

Response IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water. IF

INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTRE/doctor if you feel unwell. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. IF exposed or concerned: Get medical advice/attention. If skin irritation or rash occurs: Get medical advice/attention. If eye irritation persists: Get medical advice/attention. Take off contaminated clothing and wash it before

1 / 11

reuse.

Storage Store in a well-ventilated place. Keep container tightly closed. Keep cool. Store locked up. Protect

from sunlight. Do not expose to temperatures exceeding 50°C/122°F.

Behr Premium Aerosol - Black - Satin SDS Canada

Disposal

Dispose of contents/container in accordance with local/regional/national/international regulations.

Supplemental information

None.

Other hazards

None known.

3. Composition/information on ingredients

Mixtures

Chemical name	Common name and synonyms	CAS number	%
Acetone		67-64-1	10 - 30
Titanium dioxide		13463-67-7	10 - 30
n-Butyl acetate		123-86-4	10 - 30
Distillates (petroleum), hydrotreated light		64742-47-8	1 - 3
2-Butanone (Methyl ethyl ketone)		78-93-3	1 - 3
Naphtha (petroleum), hydrotreated heavy		64742-48-9	1 - 3
2-Butanone oxime		96-29-7	0.1 - 1
2-Ethylhexanoic acid, zirconium salt		22464-99-9	0.1 - 1
Cobalt neodecanoate		27253-31-2	0.1 - 1

Composition comments

All concentrations are in percent by weight unless ingredient is a gas. Gas concentrations are in percent by volume.

The exact concentrations of the above listed chemicals are being withheld as a trade secret.

4. First-aid measures

Inhalation

Remove victim to fresh air and keep at rest in a position comfortable for breathing. Call a poison centre or doctor/physician if you feel unwell.

Skin contact

Remove contaminated clothing immediately and wash skin with soap and water. In case of eczema or other skin disorders: Seek medical attention and take along these instructions.

Eye contact

Ingestion

Immediately flush eyes with plenty of water for at least 15 minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Get medical attention if irritation develops and persists. Not likely, due to the form of the product. In the unlikely event of swallowing contact a physician or

pois

poison control centre. Rinse mouth.

May cause drowsiness or dizziness. Headache. Nausea, vomiting. Severe eye irritation.

Most important symptoms/effects, acute and delayed

Indication of immediate medical attention and special treatment needed

Symptoms may include stinging, tearing, redness, swelling, and blurred vision. May cause an allergic skin reaction. Dermatitis. Rash. Prolonged exposure may cause chronic effects.

Provide general supportive measures and treat symptomatically. Thermal burns: Flush with water

Provide general supportive measures and treat symptomatically. Thermal burns: Flush with water immediately. While flushing, remove clothes which do not adhere to affected area. Call an ambulance. Continue flushing during transport to hospital. Keep victim under observation. Symptoms may be delayed.

General information

Take off all contaminated clothing immediately. IF exposed or concerned: Get medical advice/attention. If you feel unwell, seek medical advice (show the label where possible). Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves. Show this safety data sheet to the doctor in attendance. Wash contaminated clothing before reuse.

5. Fire-fighting measures

Suitable extinguishing media Unsuitable extinguishing media Water fog. Alcohol resistant foam. Dry chemical powder. Carbon dioxide (CO2).

Do not use water jet as an extinguisher, as this will spread the fire.

Specific hazards arising from the chemical

Vapours may form explosive mixtures with air. Vapours may travel considerable distance to a source of ignition and flash back. Contents under pressure. Pressurised container may explode when exposed to heat or flame. During fire, gases hazardous to health may be formed.

Special protective equipment and precautions for firefighters

Firefighters must use standard protective equipment including flame retardant coat, helmet with face shield, gloves, rubber boots, and in enclosed spaces, SCBA.

Fire fighting equipment/instructions

In case of fire and/or explosion do not breathe fumes. In case of fire: Stop leak if safe to do so. Do not move cargo or vehicle if cargo has been exposed to heat. If tank, rail car or tank truck is involved in a fire, ISOLATE for 800 meters (1/2 mile) in all directions; also consider initial evacuation for 800 meters (1/2 mile) in all directions. ALWAYS stay away from tanks engulfed in flame. Move containers from fire area if you can do so without risk. Containers should be cooled with water to prevent vapour pressure build up. For massive fire in cargo area, use unmanned hose holder or monitor nozzles, if possible. If not, withdraw and let fire burn out.

Specific methods

Use standard firefighting procedures and consider the hazards of other involved materials. Move containers from fire area if you can do so without risk. In the event of fire and/or explosion do not breathe fumes.

General fire hazards

Extremely flammable aerosol. Contents under pressure. Pressurised container may explode when exposed to heat or flame.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Keep out of low areas. Many gases are heavier than air and will spread along ground and collect in low or confined areas (sewers, basements, tanks). Wear appropriate protective equipment and clothing during clean-up. Avoid breathing mist/vapours. Emergency personnel need self-contained breathing equipment. Do not touch damaged containers or spilled material unless wearing appropriate protective clothing. Ventilate closed spaces before entering them. Local authorities should be advised if significant spillages cannot be contained. For personal protection, see section 8 of the SDS.

Methods and materials for containment and cleaning up

Refer to attached safety data sheets and/or instructions for use. Stop leak if you can do so without risk. Move the cylinder to a safe and open area if the leak is irreparable. Use water spray to reduce vapours or divert vapour cloud drift. Isolate area until gas has dispersed. Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area). Keep combustibles (wood, paper, oil etc) away from spilled material. Absorb in vermiculite, dry sand or earth and place into containers. Following product recovery, flush area with water.

Small Spills: Wipe up with absorbent material (e.g. cloth, fleece). Clean surface thoroughly to remove residual contamination. For waste disposal, see section 13 of the SDS.

Environmental precautions

Avoid discharge into drains, water courses or onto the ground.

7. Handling and storage

Precautions for safe handling

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Pressurised container: Do not pierce or burn, even after use. Do not use if spray button is missing or defective. Do not spray on a naked flame or any other incandescent material. Do not smoke while using or until sprayed surface is thoroughly dry. Do not cut, weld, solder, drill, grind, or expose containers to heat, flame, sparks, or other sources of ignition. All equipment used when handling the product must be grounded. Protect cylinders from physical damage; do not drag, roll, slide, or drop. Do not re-use empty containers. Do not breathe mist/vapours. Avoid contact with eyes, skin, and clothing. Avoid prolonged exposure. Pregnant or breastfeeding women must not handle this product. Use only in well-ventilated areas. Wear appropriate personal protective equipment. Observe good industrial hygiene practices.

Conditions for safe storage, including any incompatibilities

Store locked up. Pressurized container. Protect from sunlight and do not expose to temperatures exceeding 50°C. Do not puncture, incinerate or crush. Do not handle or store near an open flame, heat or other sources of ignition. This material can accumulate static charge which may cause spark and become an ignition source. Store in tightly closed container. Store in a well-ventilated place. Stored containers should be periodically checked for general condition and leakage. Store away from incompatible materials (see section 10 of the SDS).

8. Exposure controls/personal protection

Occupational exposure limits

US. ACGIH Threshold	Limit Values
Components	

Components	Туре	Value	
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	STEL	300 ppm	
	TWA	200 ppm	
2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)	STEL	10 mg/m3	
	TWA	5 mg/m3	
Acetone (CAS 67-64-1)	STEL	500 ppm	
	TWA	250 ppm	

SDS Canada

IIS ACGIH Threshold I imit Values			
	110	Throchold	Limit Values

Components	Туре	Value	
n-Butyl acetate (CAS 123-86-4)	STEL	150 ppm	
	TWA	50 ppm	
Titanium dioxide (CAS 13463-67-7)	TWA	10 mg/m3	

Canada. Alberta OELs (Occupational Health & Safety Code, Schedule 1, Table 2)

Components	Туре	Value	Form
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	STEL	885 mg/m3	
		300 ppm	
	TWA	590 mg/m3	
		200 ppm	
2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)	STEL	10 mg/m3	
	TWA	5 mg/m3	
Acetone (CAS 67-64-1)	STEL	1800 mg/m3	
		750 ppm	
	TWA	1200 mg/m3	
		500 ppm	
Distillates (petroleum), nydrotreated light (CAS 64742-47-8)	TWA	200 mg/m3	Vapour.
n-Butyl acetate (CAS 123-86-4)	STEL	950 mg/m3	
		200 ppm	
	TWA	713 mg/m3	
		150 ppm	
Titanium dioxide (CAS 13463-67-7)	TWA	10 mg/m3	

Canada. British Columbia OELs. (Occupational Exposure Limits for Chemical Substances, Occupational Health and Safety Regulation 296/97, as amended)

Components	Туре	Value	Form
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	STEL	100 ppm	
	TWA	50 ppm	
2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)	STEL	10 mg/m3	
	TWA	5 mg/m3	
Acetone (CAS 67-64-1)	STEL	500 ppm	
	TWA	250 ppm	
Distillates (petroleum), hydrotreated light (CAS 64742-47-8)	TWA	200 mg/m3	Non-aerosol.
n-Butyl acetate (CAS 123-86-4)	TWA	20 ppm	
Titanium dioxide (CAS 13463-67-7)	TWA	3 mg/m3	Respirable fraction.
		10 mg/m3	Total dust.

Behr Premium Aerosol - Black - Satin

SDS Canada

Components	Туре	Value
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	STEL	300 ppm
	TWA	200 ppm
2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)	STEL	10 mg/m3
	TWA	5 mg/m3
Acetone (CAS 67-64-1)	STEL	500 ppm
	TWA	250 ppm
n-Butyl acetate (CAS 123-86-4)	STEL	150 ppm
	TWA	50 ppm
Fitanium dioxide (CAS 13463-67-7)	TWA	10 mg/m3
Canada. Ontario OELs. (Control o	•	— ·
Components	Туре	Value
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	STEL	300 ppm
	TWA	200 ppm
2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)	STEL	10 mg/m3
	TWA	5 mg/m3
Acetone (CAS 67-64-1)	STEL	500 ppm
	TWA	250 ppm
Naphtha (petroleum), nydrotreated heavy (CAS 54742-48-9)	TWA	525 mg/m3
n-Butyl acetate (CAS 123-86-4)	STEL	150 ppm
	TWA	50 ppm
Fitanium dioxide (CAS I 3463-67-7)	TWA	10 mg/m3
Canada. Quebec OELs. (Ministry Components	of Labor - Regulation respecti Type	ng occupational health and safety) Value Form
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	STEL	300 mg/m3
		100 ppm
	TWA	150 mg/m3
		50 ppm
2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)	STEL	10 mg/m3
,	TWA	5 mg/m3
Acetone (CAS 67-64-1)	STEL	2380 mg/m3
		1000 ppm
	TWA	1190 mg/m3
		500 ppm
n-Butyl acetate (CAS 123-86-4)	STEL	950 mg/m3
		200 ppm
	TWA	

Behr Premium Aerosol - Black - Satin

SDS Canada

Components	Туре	Value	Form
		150 ppm	
Fitanium dioxide (CAS 13463-67-7)	TWA	10 mg/m3	Total dust.

Components	Type	Value	Form
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	15 minute	300 ppm	
	8 hour	200 ppm	
2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)	15 minute	10 mg/m3	
	8 hour	5 mg/m3	
Acetone (CAS 67-64-1)	15 minute	750 ppm	
	8 hour	500 ppm	
Distillates (petroleum), hydrotreated light (CAS 64742-47-8)	15 minute	250 mg/m3	Vapour.
	8 hour	200 mg/m3	Vapour.
n-Butyl acetate (CAS 123-86-4)	15 minute	200 ppm	
	8 hour	150 ppm	
Titanium dioxide (CAS 13463-67-7)	15 minute	20 mg/m3	
	8 hour	10 mg/m3	

Biological limit values

ACGIH Biological Exposure Indices

Components	Value	Determinant	Specimen	Sampling Time
2-Butanone (Methyl ethyl ketone) (CAS 78-93-3)	2 mg/l	MEK	Urine	*
Acetone (CAS 67-64-1)	25 mg/l	Acetone	Urine	*

^{* -} For sampling details, please see the source document.

Exposure guidelines

Canada - Alberta OELs: Skin designation

(CAS 64742-47-8)

Canada - British Columbia OELs: Skin designation

Distillates (petroleum), hydrotreated light Can be absorbed through the skin.

(CAS 64742-47-8)

Canada - Saskatchewan OELs: Skin designation

(CAS 64742-47-8)

Appropriate engineering controls

Appropriate engineeringGood general ventilation should be used. Ventilation rates should be matched to conditions. If

applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. Provide eyewash station and safety

shower.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Hand protectionWear appropriate chemical resistant gloves.OtherWear appropriate chemical resistant clothing.

Behr Premium Aerosol - Black - Satin

Respiratory protection When workers are facing concentrations above the exposure limit they must use appropriate

certified respirators. Chemical respirator with organic vapour cartridge and full facepiece. Use a positive-pressure air-supplied respirator if there is any potential for an uncontrolled release, exposure levels are not known, or any other circumstances where air-purifying respirators may not

provide adequate protection.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

Observe any medical surveillance requirements. When using do not smoke. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants.

9. Physical and chemical properties

Appearance

Physical state Liquid. **Form** Aerosol. Black. Colour Odour Solvent. **Odour threshold** Not available. Not available. nΗ Not available. Melting point/freezing point Initial boiling point and boiling Not available.

range

Flash point -104.444 °C (-156 °F)

Evaporation rate Not available.

Flammability (solid, gas) Not applicable.

Upper/lower flammability or explosive limits

Explosive limit - lower (%) Not available.

Explosive limit - upper Not available.

(%)

Vapour pressureNot available.Vapour densityNot available.Relative densityNot available.

Solubility(ies)

Solubility (water) Not available.

Partition coefficient Not available.

(n-octanol/water)

Auto-ignition temperature Not available.

Decomposition temperature Not available.

Viscosity Not available.

Other information

Density7.2 lbs/galExplosive propertiesNot explosive.Oxidising propertiesNot oxidising.VOCMIR <0.95</th>

10. Stability and reactivity

ReactivityThe product is stable and non-reactive under normal conditions of use, storage and transport.

Chemical stability Material is stable under normal conditions.

Possibility of hazardous

reactions

No dangerous reaction known under conditions of normal use.

Conditions to avoid Heat. Avoid temperatures exceeding the flash point. Contact with incompatible materials.

Incompatible materials Strong oxidising agents.

Hazardous decompositionNo hazardous decomposition products are known.

products

Behr Premium Aerosol - Black - Satin

SDS Canada

11. Toxicological information

Information on likely routes of exposure

May cause drowsiness or dizziness. Prolonged inhalation may be harmful. Inhalation

May cause an allergic skin reaction. Skin contact

Eye contact Causes serious eye irritation.

Ingestion Expected to be a low ingestion hazard.

Symptoms related to the physical, chemical and toxicological characteristics May cause drowsiness or dizziness. Headache. Nausea, vomiting. Severe eye irritation. Symptoms may include stinging, tearing, redness, swelling, and blurred vision. May cause an

allergic skin reaction. Dermatitis. Rash.

Information on toxicological effects

Acute toxicity

Components	Species	Test Results
2-Butanone (Methyl ethyl ke	tone) (CAS 78-93-3)	
<u>Acute</u>		
Dermal		
LD50	Rat	6400 mg/kg
Inhalation		
Vapour		
LC50	Rat	34.5 mg/l, 4 Hours
Oral	_	
LD50	Rat	2600 mg/kg
2-Butanone oxime (CAS 96-	-29-7)	
Acute		
Dermal	D 11.7	4000 // 0411
LD50	Rabbit	> 1000 mg/kg, 24 Hours
Oral	D /	000 #
LD50	Rat	> 900 mg/kg
Acetone (CAS 67-64-1)		
Acute .		
Dermal LD50	Rabbit	45700 mg/kg 24 Hours
	Rappit	> 15700 mg/kg, 24 Hours
Inhalation		
<i>Vapour</i> LC50	Rat	76 mg/l, 4 Hours
Oral	rec	ro mg/i, + mours
LD50	Rat	5800 mg/kg
	treated heavy (CAS 64742-48-9)	oooo mg ng
Acute	ireated reavy (CAC 04742-40-3)	
<u> Dermal</u>		
LD50	Rabbit	> 2000 mg/kg
Inhalation		0 0
LC50	Rat	> 4.96 mg/l, 4 Hours
Oral		·
LD50	Rat	> 5000 mg/kg
n-Butyl acetate (CAS 123-86		
<u>Acute</u>		
Inhalation		
LC50	Rat	2000 ppm, 4 Hours
Oral		
LD50	Rat	10770 mg/kg

Behr Premium Aerosol - Black - Satin 958851 Version #: 01 Revision date: -Issue date: 06-July-2021 Components Species Test Results

Titanium dioxide (CAS 13463-67-7)

Acute Oral

LD50 Rat > 5000 mg/kg

Skin corrosion/irritation Prolonged skin contact may cause temporary irritation.

Serious eye damage/eye

irritation

Causes serious eye irritation.

Respiratory or skin sensitisation

Canada - Alberta OELs: Irritant

n-Butyl acetate (CAS 123-86-4) Irritant
Titanium dioxide (CAS 13463-67-7) Irritant

Respiratory sensitisation Not a respiratory sensitiser.

Skin sensitisation May cause an allergic skin reaction.

Germ cell mutagenicity

No data available to indicate product or any components present at greater than 0.1% are

mutagenic or genotoxic.

Carcinogenicity May cause cancer.

ACGIH Carcinogens

2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9)
Acetone (CAS 67-64-1)
A4 Not classifiable as a human carcinogen.

Titanium dioxide (CAS 13463-67-7)

Canada - Manitoba OELs: carcinogenicity

2-Ethylhexanoic acid, zirconium salt (CAS 22464-99-9) Not classifiable as a human carcinogen.

Acetone (CAS 67-64-1)

Not classifiable as a human carcinogen.

Titanium dioxide (CAS 13463-67-7)

Not classifiable as a human carcinogen.

IARC Monographs. Overall Evaluation of Carcinogenicity

Naphtha (petroleum), hydrotreated heavy

3 Not classifiable as to carcinogenicity to humans.

(CAS 64742-48-9)

Titanium dioxide (CAS 13463-67-7) 2B Possibly carcinogenic to humans.

US. National Toxicology Program (NTP) Report on Carcinogens

Cobalt neodecanoate (CAS 27253-31-2)

Reasonably Anticipated to be a Human Carcinogen.

Reproductive toxicity Suspected of damaging the unborn child.

Specific target organ toxicity -

single exposure

May cause drowsiness or dizziness.

Specific target organ toxicity -

repeated exposure

Not classified.

Aspiration hazard Not an aspiration hazard.

Chronic effects Prolonged inhalation may be harmful.

12. Ecological information

Ecotoxicity Harmful to aquatic life with long lasting effects.

Persistence and degradability No data is available on the degradability of this product.

Bioaccumulative potential

Partition coefficient n-octanol / water (log Kow)

n-Butyl acetate (CAS 123-86-4) 1.78

Mobility in soil No data available.

Other adverse effects

The product contains volatile organic compounds which have a photochemical ozone creation

potential.

13. Disposal considerations

Disposal instructionsCollect and reclaim or dispose in sealed containers at licensed waste disposal site. Contents

under pressure. Do not puncture, incinerate or crush. Dispose of contents/container in accordance

with local/regional/national/international regulations.

Local disposal regulations Dispose in accordance with all applicable regulations.

Hazardous waste codeThe waste code should be assigned in discussion between the user, the producer and the waste

disposal company.

Waste from residues / unused

products

Dispose in accordance with local regulations. Empty containers or liners may retain some product residues. This material and its container must be disposed of in a safe manner (see: Disposal

instructions).

Contaminated packaging

Since emptied containers may retain product residue, follow label warnings even after container is emptied. Empty containers should be taken to an approved waste handling site for recycling or disposal. Do not re-use empty containers.

14. Transport information

TDG

UN1950 **UN number** UN proper shipping name **AEROSOLS**

Transport hazard class(es)

Class 2.1 Subsidiary risk Packing group No **Environmental hazards**

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

IATA

UN1950 **UN** number Aerosols **UN** proper shipping name

Transport hazard class(es)

2.1 Class Subsidiary risk Packing group **Environmental hazards** No **ERG Code** 10L

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

IMDG

UN1950 **UN** number **UN** proper shipping name **AEROSOLS**

Transport hazard class(es)

Class 2.1 Subsidiary risk Packing group **Environmental hazards**

Marine pollutant No F-D. S-U **EmS**

Transport in bulk according to

Special precautions for user Read safety instructions, SDS and emergency procedures before handling. Not applicable.

Annex II of MARPOL 73/78 and

the IBC Code

15. Regulatory information

Canadian regulations This product has been classified in accordance with the hazard criteria of the HPR and the SDS contains all the information required by the HPR.

Canada. Excluded VOCs. Guidelines for Volatile Organic Compounds in Consumer Products. CEPA 1999. Environment Canada, as amended

Acetone (CAS 67-64-1)

Controlled Drugs and Substances Act

Not regulated.

Export Control List (CEPA 1999, Schedule 3)

Not listed.

Greenhouse Gases

Not listed.

Ontario. Toxic Substances. Toxic Reduction Act, 2009. Regulation 455/09 (July 1, 2011)

Acetone (CAS 67-64-1)

Cobalt neodecanoate (CAS 27253-31-2)

Precursor Control Regulations

2-Butanone (Methyl ethyl ketone) (CAS 78-93-3) Class B Class B Acetone (CAS 67-64-1)

Behr Premium Aerosol - Black - Satin 958851 Version #: 01 Revision date: -Issue date: 06-July-2021

International regulations

Stockholm Convention

Not applicable.

Rotterdam Convention

Not applicable.

Kyoto Protocol

Not applicable.

Montreal Protocol

Not applicable.

Basel Convention

Not applicable.

16. Other information

Issue date 06-July-2021

Revision date Version No. 01

List of abbreviations IATA: International Air Transport Association.

IBC Code: International Code for the Construction and Equipment of Ships Carrying Dangerous

Chemicals in Bulk.

IMDG Code: International Maritime Dangerous Goods Code.

LC50: Lethal Concentration, 50%.

LD50: Lethal Dose, 50%.

MARPOL: International Convention for the Prevention of Pollution from Ships.

STEL: Short-Term Exposure Limit.

TDG: Transportation of Dangerous Goods. TWA: Time Weighted Average Value.

HSDB® - Hazardous Substances Data Bank References

Disclaimer Behr Process Corp cannot anticipate all conditions under which this information and its product, or

the products of other manufacturers in combination with its product, may be used. It is the user's responsibility to ensure safe conditions for handling, storage and disposal of the product, and to assume liability for loss, injury, damage or expense due to improper use. The information in the

sheet was written based on the best knowledge and experience currently available.

Behr Premium Aerosol - Black - Satin