

Safety Issue Type: Manufacturer Communications

June 01 2004 Manufacturer Communication Number: 10014213

Components: STRUCTURE

NHTSA ID Number 10014213

Manufacturer Communication Number 06012004

Summary

RODENT DAMAGE TO KNOCK SENSOR SUBHARNESS. *SC

Affected Products (10)

Vehicle

MAKE	MODEL	YEAR
HONDA	ACCORD	2003-2004
HONDA	ODYSSEY	1999-2004
HONDA	PILOT	2003-2004