

MARIN MOUNTAIN BIKES IMPORTANT SAFETY NOTICE



HAZARD

The bottom bracket on some model year 2021 Marin Bikes can break during use, causing the rider to lose control, posing fall and crash hazards to the user. A limited number of the below listed bicycle models were assembled using a defective bottom bracket. Not all bicycles sold in 2021 are affected.

AFFECTED MODEL YEAR 2021 MARIN BIKES

SAN QUENTIN 1	WILDCAT TRAIL 3	TERRA LINDA 2	SAN ANSELMO DS2	SAN RAFAEL DS1
SAN QUENTIN 20"	FAIRFAX 1	PRESIDIO 3	LARKSPUR 1	SAN RAFAEL DS2
SAN QUENTIN 24"	FAIRFAX 2	KENTFIELD 2	MUIRWOODS RC	HIDDEN CANYON 20"
WILDCAT TRAIL 1	TERRA LINDA 1	KENTFIELD 2 ST	SAN ANSELMO DS1	BAYVIEW TRAIL 24"

HOW TO IDENTIFY THE AFFECTED BIKES?

Go to www.marinbikes.com/bikes/recalls-safety and click on the "2021 Bottom Bracket Recall" link or visit your Marin dealer.

REMEDY: REPAIR

Consumers should immediately stop using the recalled bicycle and contact a Marin dealer to receive a free replacement bottom bracket.

You can contact Marin a number of ways:

- Through our web site at www.marinbikes.com/bikes/recalls-safety
- Via email, at "recall@marinbikes.com"
- Call (800) 222-7557 (option 7) from 9 a.m. to 5 p.m. PT Monday through Friday

Marin authorized retailers will replace the affected bottom bracket (free of charge). No other part of the bicycles is affected.

We sincerely apologize for the inconvenience and thank you for your cooperation in this important safety program. This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission