

# SCHOOL INSPECTION PROGRESS REPORT

**School:** West Royalty Elementary School, Eastern School District

**Date:** August 25, 2011

Room # / Description	Observations	Level of Remediation	Status
Room 138, 123, 143, 149, 167, 181, 183	Stained ceiling tiles.	Removal of stained ceiling tiles to further investigate for potential hidden mould above ceiling. Replace with new tiles to detect new water leaks.	Tiles replaced March/'11, monitoring for any signs of water infiltration
Room 118 Sprinkler	Visible mould on pipe insulation.	Have area cleaned and decontaminated using Level 1 precautions by custodial staff.	Mould remediation complete

## Conclusion and Recommendations:

Faculty and staff are asked to report any signs of water infiltration and/or mould to their Property Services Manager so that water infiltration is repaired and any mould which may have developed is remediated right away.

**For more information on the School Inspection program, please visit:**

[www.gov.pe.ca/eedd/schoolinspections](http://www.gov.pe.ca/eedd/schoolinspections)