



SERVICE BULLETIN

No. 376

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA SO-1 Approved"

April 19, 1973 S

Subject: Fuel Selector Control System Modification

Models Affected:
PA-28-235 Cherokee
PA-32-260 Cherokee Six
PA-32-300 Cherokee Six
PA-32S-300 Cherokee Six

Serial Numbers Affected:
28-10001 to 28-7310125 incl.
32-03, 32-04, 32-1 to 32-7300036 incl.
32-15, 32-21, 32-4000 to 32-7340081 incl.
32S-40000 to 32S-7240110 incl.

Compliance Time: Within the next 100 hours of operation, or at the next 100-hour inspection or annual inspection, whichever occurs first.

Purpose: To provide material and instructions to modify the fuel selector control system on the above referenced aircraft. Installation of the appropriate fuel selector control modification kit provides a more serviceable fuel tank selection system.

Instructions: Contained in appropriate fuel selector control modification kit (see Material Required, below).

Material Required:

<u>Part Number</u>	<u>Model</u>	<u>Serial Numbers Affected</u>	<u>Nomenclature</u>
760 681V	PA-28-235	28-10001 to 28-10785 incl.	Kit-Fuel Selector Control Modification
760 682V	PA-28-235	28-10786 to 28-11039 incl.	Kit-Fuel Selector Control Modification
760 683V	PA-28-235	28-11040 to 28-11300 incl.	Kit-Fuel Selector Control Modification
760 684V	PA-28-235	28-11301 to 28-7310125 incl.	Kit-Fuel Selector Control Modification
760 685V	PA-32-260	32-03, 32-04, 32-1 to 32-875 incl.	Kit-Fuel Selector Control Modification
760 686V	PA-32-260	32-876 to 32-1110 incl.	Kit-Fuel Selector Control Modification
760 686V	PA-32-300	32-15, 32-21, 32-40000 to 32-40565 incl.	Kit-Fuel Selector Control Modification
760 686V	PA-32S-300	32S-15, 32S-40000 to 32S-40565 incl.	Kit-Fuel Selector Control Modification
760 687V	PA-32-260	32-1111 to 32-1250 incl.	Kit-Fuel Selector Control Modification
760 687V	PA-32-300	32-40566 to 32-40850 incl.	Kit-Fuel Selector Control Modification
760 687V	PA-32S-300	32S-40566 to 32S-40850 incl.	Kit-Fuel Selector Control Modification
760 688V	PA-32-260	32-1251 to 32-7300036 incl.	Kit-Fuel Selector Control Modification
760 688V	PA-32-300	32-40851 to 32-7340081 incl.	Kit-Fuel Selector Control Modification
760 688V	PA-32S-300	32S-40851 to 32S-7240110 incl.	Kit-Fuel Selector Control Modification

Material Required: (continued)

NOTE:

A new Fuel Selector Control Cover (Upper) will be provided with the above referenced kits; therefore, the color of your existing Fuel Selector Control Cover Assembly must be provided with your order.

Availability of Parts:

Your Piper Dealer.

Effectivity Date:

This Service Bulletin is effective May 14, 1973.

Summary:

Please contact your Piper Dealer to make arrangements for compliance with this service release in accordance with the provisions of Compliance Time, above. Material associated with this service release is provided free of charge and a pro-rated labor allowance program is available to affected owners/operators through your Piper Dealer providing the applicable installation is accomplished by a Piper Dealer; material and labor allowance provisions of this Service Bulletin expire November 30, 1973.

A Service Publication Compliance Form accompanies each copy of this Service Bulletin mailed to affected owners of record. This is to be filled out according to directions on the form and left with the Piper Dealer performing the modification.